

LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATION NO:	QC-SLB-25185-04	
LOCATION:	SLICK LINE WORKSHOP			
EXAMINATION DATE:	15/Jul/2025	JOB NO:	QC-SLB-25185	
LAST INSPECTION		NEXT INSPECTION DATE		LAST PROOF LOAD TEST DATE
21/Jan/2025		14/Jan/2026		BY MANUFACTURE
IDENTIFICATION NO	DESCRIPTION		QTY	SWL
NE3942	<u>Single Leg Wire Rope Sling.</u> Diameter: 13 mm Length: 10 FT IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE HARD EYE AT BOTH END SAFETY FACTOR 5:1		01	2.1 TON
Applicable Reference Standard:	BS EN 13414-1:2003+A2:2008			
* Is this the first examination after installation or assembly at a new site or location?	YES		NO	
	YES		NO	
* If the answer to the above question is YES has the equipment been installed correctly?	YES		NO	
	YES		NO	
Was the examination carried out?				
* Within an interval of 6 months?		YES		NO
* Within an interval of 12 months?		YES		NO
* By an examination scheme?		YES		NO
* After the occurrence of exceptional circumstances?		YES		NO
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None				
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES		NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)		NO		YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None				
** Visual And Dimension Check was Carried Out.				
Is This Equipment Safe To Operate?		Yes Accept		NO Reject

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohammad Abdullah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT; a competent person of Takamul Company has examined the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.