



## Borescope Examination Report

|                             |                                              |                          |               |                        |                        |
|-----------------------------|----------------------------------------------|--------------------------|---------------|------------------------|------------------------|
| <b>Client Name:</b>         | Daqing Drilling Company                      | <b>Location:</b>         | Rig (DQ 1202) | <b>Job Number:</b>     | QC-DQ-04-24-0138       |
| <b>Date of Examination:</b> | 03-05-2024                                   | <b>Date of Report:</b>   | 03-05-2024    | <b>Certificate No:</b> | QC-DQ-04-24-0138-31-01 |
| <b>Serial Number</b>        | <b>Description of the examined equipment</b> | <b>Manufacturer Date</b> |               | <b>Result</b>          |                        |
| 1026942                     | ROTARY HOSE                                  | 17-01-2023               |               | Accepted               |                        |



### Equipment Details

|                    |                             |                       |                    |             |           |
|--------------------|-----------------------------|-----------------------|--------------------|-------------|-----------|
| <b>Standard</b>    | API Spec 7k<br>API Spec 16C | <b>Equipment type</b> | Borescope<br>MIQAS | <b>S/N:</b> | M22030007 |
| <b>Test Method</b> | Visual Test (Inside Hose)   |                       |                    |             |           |

### Procedure

Check inside for any damage and wear and distortion by using Borescope camera. Visual carried out for the above description and found free of inside defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

None

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

None

|                                      |                                                                                      |                                          |
|--------------------------------------|--------------------------------------------------------------------------------------|------------------------------------------|
| <b>ASNT Level II Inspector Name:</b> | <b>Signature &amp; Stamp:</b>                                                        | <b>Date of Next Through Examination:</b> |
| Abdullah Mofeed                      |  | As Per Client Request                    |

REV: 01 Dated: 20 June 2022





## Borescope Examination Report

|                             |                                              |                        |                          |                        |                        |
|-----------------------------|----------------------------------------------|------------------------|--------------------------|------------------------|------------------------|
| <b>Client Name:</b>         | Daqing Drilling Company                      | <b>Location:</b>       | Rig (DQ 1202)            | <b>Job Number:</b>     | QC-DQ-04-24-0138       |
| <b>Date of Examination:</b> | 03-05-2024                                   | <b>Date of Report:</b> | 03-05-2024               | <b>Certificate No:</b> | QC-DQ-04-24-0138-31-02 |
| <b>Serial Number</b>        | <b>Description of the examined equipment</b> |                        | <b>Manufacturer Date</b> |                        | <b>Result</b>          |
| 1026942                     | ROTARY HOSE                                  |                        | 17-01-2023               |                        | Accepted               |



### Equipment Details

|                    |                             |                       |                    |             |           |
|--------------------|-----------------------------|-----------------------|--------------------|-------------|-----------|
| <b>Standard</b>    | API Spec 7k<br>API Spec 16C | <b>Equipment type</b> | Borescope<br>MIQAS | <b>S/N:</b> | M22030007 |
| <b>Test Method</b> | Visual Test (Inside Hose)   |                       |                    |             |           |

### Procedure

Check inside for any damage and wear and distortion by using Borescope camera. Visual carried out for the above description and found free of inside defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

None

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

None

|                                      |                                                                                      |                                          |
|--------------------------------------|--------------------------------------------------------------------------------------|------------------------------------------|
| <b>ASNT Level II Inspector Name:</b> | <b>Signature &amp; Stamp:</b>                                                        | <b>Date of Next Through Examination:</b> |
| Abdullah Mofeed                      |  | As Per Client Request                    |


REV: 01 Dated: 20 June 2022





## Borescope Examination Report

|                             |                                              |                        |                          |                        |                        |
|-----------------------------|----------------------------------------------|------------------------|--------------------------|------------------------|------------------------|
| <b>Client Name:</b>         | Daqing Drilling Company                      | <b>Location:</b>       | Rig (DQ 1202)            | <b>Job Number:</b>     | QC-DQ-04-24-0138       |
| <b>Date of Examination:</b> | 03-05-2024                                   | <b>Date of Report:</b> | 03-05-2024               | <b>Certificate No:</b> | QC-DQ-04-24-0138-31-03 |
| <b>Serial Number</b>        | <b>Description of the examined equipment</b> |                        | <b>Manufacturer Date</b> |                        | <b>Result</b>          |
| 2020091444522               | MUD PUMP HOSE                                |                        | 17-01-2023               |                        | <b>Accepted</b>        |



### Equipment Details

|                    |                             |                       |                    |             |           |
|--------------------|-----------------------------|-----------------------|--------------------|-------------|-----------|
| <b>Standard</b>    | API Spec 7k<br>API Spec 16C | <b>Equipment type</b> | Borescope<br>MIQAS | <b>S/N:</b> | M22030007 |
| <b>Test Method</b> | Visual Test (Inside Hose)   |                       |                    |             |           |

### Procedure

Check inside for any damage and wear and distortion by using Borescope camera. Visual carried out for the above description and found free of inside defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

**None**

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

**None**

|                                      |                                                                                      |                                          |
|--------------------------------------|--------------------------------------------------------------------------------------|------------------------------------------|
| <b>ASNT Level II Inspector Name:</b> | <b>Signature &amp; Stamp:</b>                                                        | <b>Date of Next Through Examination:</b> |
| <b>Abdullah Mofeed</b>               |  | <b>As Per Client Request</b>             |

REV: 01 Dated: 20 June 2022





## Borescope Examination Report

|                             |                                              |                        |                          |                        |                        |
|-----------------------------|----------------------------------------------|------------------------|--------------------------|------------------------|------------------------|
| <b>Client Name:</b>         | Daqing Drilling Company                      | <b>Location:</b>       | Rig (DQ 1202)            | <b>Job Number:</b>     | QC-DQ-04-24-0138       |
| <b>Date of Examination:</b> | 03-05-2024                                   | <b>Date of Report:</b> | 03-05-2024               | <b>Certificate No:</b> | QC-DQ-04-24-0138-31-04 |
| <b>Serial Number</b>        | <b>Description of the examined equipment</b> |                        | <b>Manufacturer Date</b> |                        | <b>Result</b>          |
| 2020091444520               | MUD PUMP HOSE                                |                        | 17-01-2023               |                        | Accepted               |



### Equipment Details

|                    |                             |                       |                    |             |           |
|--------------------|-----------------------------|-----------------------|--------------------|-------------|-----------|
| <b>Standard</b>    | API Spec 7k<br>API Spec 16C | <b>Equipment type</b> | Borescope<br>MIQAS | <b>S/N:</b> | M22030007 |
| <b>Test Method</b> | Visual Test (Inside Hose)   |                       |                    |             |           |

### Procedure

Check inside for any damage and wear and distortion by using Borescope camera. Visual carried out for the above description and found free of inside defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

None

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

None

|                                      |                                                                                      |                                          |
|--------------------------------------|--------------------------------------------------------------------------------------|------------------------------------------|
| <b>ASNT Level II Inspector Name:</b> | <b>Signature &amp; Stamp:</b>                                                        | <b>Date of Next Through Examination:</b> |
| Abdullah Mofeed                      |  | As Per Client Request                    |


REV: 01 Dated: 20 June 2022





## Borescope Examination Report

|                             |                                              |                        |                          |                        |                        |
|-----------------------------|----------------------------------------------|------------------------|--------------------------|------------------------|------------------------|
| <b>Client Name:</b>         | Daqing Drilling Company                      | <b>Location:</b>       | Rig (DQ 1202)            | <b>Job Number:</b>     | QC-DQ-04-24-0138       |
| <b>Date of Examination:</b> | 03-05-2024                                   | <b>Date of Report:</b> | 03-05-2024               | <b>Certificate No:</b> | QC-DQ-04-24-0138-31-05 |
| <b>Serial Number</b>        | <b>Description of the examined equipment</b> |                        | <b>Manufacturer Date</b> |                        | <b>Result</b>          |
| 2020091444521               | MUD PUMP HOSE                                |                        | 17-01-2023               |                        | <b>Accepted</b>        |



### Equipment Details

|                    |                             |                       |                    |             |           |
|--------------------|-----------------------------|-----------------------|--------------------|-------------|-----------|
| <b>Standard</b>    | API Spec 7k<br>API Spec 16C | <b>Equipment type</b> | Borescope<br>MIQAS | <b>S/N:</b> | M22030007 |
| <b>Test Method</b> | Visual Test (Inside Hose)   |                       |                    |             |           |

### Procedure

Check inside for any damage and wear and distortion by using Borescope camera. Visual carried out for the above description and found free of inside defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

**None**

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

**None**

|                                      |                                                                                      |                                          |
|--------------------------------------|--------------------------------------------------------------------------------------|------------------------------------------|
| <b>ASNT Level II Inspector Name:</b> | <b>Signature &amp; Stamp:</b>                                                        | <b>Date of Next Through Examination:</b> |
| <b>Abdullah Mofeed</b>               |  | <b>As Per Client Request</b>             |

REV: 01 Dated: 20 June 2022





## Borescope Examination Report

|                             |                                              |                        |                          |                        |                        |
|-----------------------------|----------------------------------------------|------------------------|--------------------------|------------------------|------------------------|
| <b>Client Name:</b>         | Daqing Drilling Company                      | <b>Location:</b>       | Rig (DQ 1202)            | <b>Job Number:</b>     | QC-DQ-04-24-0138       |
| <b>Date of Examination:</b> | 03-05-2024                                   | <b>Date of Report:</b> | 03-05-2024               | <b>Certificate No:</b> | QC-DQ-04-24-0138-31-06 |
| <b>Serial Number</b>        | <b>Description of the examined equipment</b> |                        | <b>Manufacturer Date</b> |                        | <b>Result</b>          |
| 2023031140850               | CHOCK MANIFOLD HOSE                          |                        | 17-01-2023               |                        | Accepted               |



### Equipment Details

|                    |                             |                       |                    |             |           |
|--------------------|-----------------------------|-----------------------|--------------------|-------------|-----------|
| <b>Standard</b>    | API Spec 7k<br>API Spec 16C | <b>Equipment type</b> | Borescope<br>MIQAS | <b>S/N:</b> | M22030007 |
| <b>Test Method</b> | Visual Test (Inside Hose)   |                       |                    |             |           |

### Procedure

Check inside for any damage and wear and distortion by using Borescope camera. Visual carried out for the above description and found free of inside defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

None

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

None

|                                      |                                                                                      |                                          |
|--------------------------------------|--------------------------------------------------------------------------------------|------------------------------------------|
| <b>ASNT Level II Inspector Name:</b> | <b>Signature &amp; Stamp:</b>                                                        | <b>Date of Next Through Examination:</b> |
| Abdullah Mofeed                      |  | As Per Client Request                    |

REV: 01 Dated: 20 June 2022





## Borescope Examination Report

|                             |                                              |                        |                          |                        |                        |
|-----------------------------|----------------------------------------------|------------------------|--------------------------|------------------------|------------------------|
| <b>Client Name:</b>         | Daqing Drilling Company                      | <b>Location:</b>       | Rig (DQ 1202)            | <b>Job Number:</b>     | QC-DQ-04-24-0138       |
| <b>Date of Examination:</b> | 03-05-2024                                   | <b>Date of Report:</b> | 03-05-2024               | <b>Certificate No:</b> | QC-DQ-04-24-0138-31-07 |
| <b>Serial Number</b>        | <b>Description of the examined equipment</b> |                        | <b>Manufacturer Date</b> |                        | <b>Result</b>          |
| 2023031140846               | CHOCK MANIFOLD HOSE                          |                        | 17-01-2023               |                        | <b>Accepted</b>        |



### Equipment Details

|                    |                             |                       |                    |             |           |
|--------------------|-----------------------------|-----------------------|--------------------|-------------|-----------|
| <b>Standard</b>    | API Spec 7k<br>API Spec 16C | <b>Equipment type</b> | Borescope<br>MIQAS | <b>S/N:</b> | M22030007 |
| <b>Test Method</b> | Visual Test (Inside Hose)   |                       |                    |             |           |

### Procedure

Check inside for any damage and wear and distortion by using Borescope camera. Visual carried out for the above description and found free of inside defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

**None**

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

**None**

|                                      |                                                                                      |                                          |
|--------------------------------------|--------------------------------------------------------------------------------------|------------------------------------------|
| <b>ASNT Level II Inspector Name:</b> | <b>Signature &amp; Stamp:</b>                                                        | <b>Date of Next Through Examination:</b> |
| <b>Abdullah Mofeed</b>               |  | <b>As Per Client Request</b>             |

REV: 01 Dated: 20 June 2022





## Borescope Examination Report

|                             |                                              |                        |                          |                        |                        |
|-----------------------------|----------------------------------------------|------------------------|--------------------------|------------------------|------------------------|
| <b>Client Name:</b>         | Daqing Drilling Company                      | <b>Location:</b>       | Rig (DQ 1202)            | <b>Job Number:</b>     | QC-DQ-04-24-0138       |
| <b>Date of Examination:</b> | 03-05-2024                                   | <b>Date of Report:</b> | 03-05-2024               | <b>Certificate No:</b> | QC-DQ-04-24-0138-31-08 |
| <b>Serial Number</b>        | <b>Description of the examined equipment</b> |                        | <b>Manufacturer Date</b> |                        | <b>Result</b>          |
| 210712-102                  | CHOCK MANIFOLD HOSE                          |                        | 17-01-2023               |                        | <b>Accepted</b>        |



### Equipment Details

|                    |                             |                       |                    |             |           |
|--------------------|-----------------------------|-----------------------|--------------------|-------------|-----------|
| <b>Standard</b>    | API Spec 7k<br>API Spec 16C | <b>Equipment type</b> | Borescope<br>MIQAS | <b>S/N:</b> | M22030007 |
| <b>Test Method</b> | Visual Test (Inside Hose)   |                       |                    |             |           |

### Procedure

Check inside for any damage and wear and distortion by using Borescope camera. Visual carried out for the above description and found free of inside defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

**None**

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

**None**

|                                      |                                                                                      |                                          |
|--------------------------------------|--------------------------------------------------------------------------------------|------------------------------------------|
| <b>ASNT Level II Inspector Name:</b> | <b>Signature &amp; Stamp:</b>                                                        | <b>Date of Next Through Examination:</b> |
| <b>Abdullah Mofeed</b>               |  | <b>As Per Client Request</b>             |


REV: 01 Dated: 20 June 2022





## Borescope Examination Report

|                             |                                              |                        |                          |                        |                        |
|-----------------------------|----------------------------------------------|------------------------|--------------------------|------------------------|------------------------|
| <b>Client Name:</b>         | Daqing Drilling Company                      | <b>Location:</b>       | Rig (DQ 1202)            | <b>Job Number:</b>     | QC-DQ-04-24-0138       |
| <b>Date of Examination:</b> | 03-05-2024                                   | <b>Date of Report:</b> | 03-05-2024               | <b>Certificate No:</b> | QC-DQ-04-24-0138-31-09 |
| <b>Serial Number</b>        | <b>Description of the examined equipment</b> |                        | <b>Manufacturer Date</b> |                        | <b>Result</b>          |
| 210106-101                  | CHOCK MANIFOLD HOSE                          |                        | 17-01-2023               |                        | <b>Accepted</b>        |



### Equipment Details

|                    |                             |                       |                    |             |           |
|--------------------|-----------------------------|-----------------------|--------------------|-------------|-----------|
| <b>Standard</b>    | API Spec 7k<br>API Spec 16C | <b>Equipment type</b> | Borescope<br>MIQAS | <b>S/N:</b> | M22030007 |
| <b>Test Method</b> | Visual Test (Inside Hose)   |                       |                    |             |           |

### Procedure

Check inside for any damage and wear and distortion by using Borescope camera. Visual carried out for the above description and found free of inside defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

**None**

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

**None**

|                                      |                                                                                      |                                          |
|--------------------------------------|--------------------------------------------------------------------------------------|------------------------------------------|
| <b>ASNT Level II Inspector Name:</b> | <b>Signature &amp; Stamp:</b>                                                        | <b>Date of Next Through Examination:</b> |
| <b>Abdullah Mofeed</b>               |  | <b>As Per Client Request</b>             |

REV: 01 Dated: 20 June 2022





## Borescope Examination Report

|                             |                                              |                        |                          |                        |                        |
|-----------------------------|----------------------------------------------|------------------------|--------------------------|------------------------|------------------------|
| <b>Client Name:</b>         | Daqing Drilling Company                      | <b>Location:</b>       | Rig (DQ 1202)            | <b>Job Number:</b>     | QC-DQ-04-24-0138       |
| <b>Date of Examination:</b> | 03-05-2024                                   | <b>Date of Report:</b> | 03-05-2024               | <b>Certificate No:</b> | QC-DQ-04-24-0138-31-10 |
| <b>Serial Number</b>        | <b>Description of the examined equipment</b> |                        | <b>Manufacturer Date</b> |                        | <b>Result</b>          |
| 514525                      | KILL LINE HOSE                               |                        | 17-01-2023               |                        | Accepted               |



### Equipment Details

|                    |                             |                       |                    |             |           |
|--------------------|-----------------------------|-----------------------|--------------------|-------------|-----------|
| <b>Standard</b>    | API Spec 7k<br>API Spec 16C | <b>Equipment type</b> | Borescope<br>MIQAS | <b>S/N:</b> | M22030007 |
| <b>Test Method</b> | Visual Test (Inside Hose)   |                       |                    |             |           |

### Procedure

Check inside for any damage and wear and distortion by using Borescope camera. Visual carried out for the above description and found free of inside defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

None

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

None

|                                      |                                                                                      |                                          |
|--------------------------------------|--------------------------------------------------------------------------------------|------------------------------------------|
| <b>ASNT Level II Inspector Name:</b> | <b>Signature &amp; Stamp:</b>                                                        | <b>Date of Next Through Examination:</b> |
| Abdullah Mofeed                      |  | As Per Client Request                    |

REV: 01 Dated: 20 June 2022





## Borescope Examination Report

|                             |                                              |                        |                          |                        |                        |
|-----------------------------|----------------------------------------------|------------------------|--------------------------|------------------------|------------------------|
| <b>Client Name:</b>         | Daqing Drilling Company                      | <b>Location:</b>       | Rig (DQ 1202)            | <b>Job Number:</b>     | QC-DQ-04-24-0138       |
| <b>Date of Examination:</b> | 03-05-2024                                   | <b>Date of Report:</b> | 03-05-2024               | <b>Certificate No:</b> | QC-DQ-04-24-0138-31-11 |
| <b>Serial Number</b>        | <b>Description of the examined equipment</b> |                        | <b>Manufacturer Date</b> |                        | <b>Result</b>          |
| 514469                      | KILL LINE HOSE                               |                        | 17-01-2023               |                        | Accepted               |



### Equipment Details

|                    |                             |                       |                    |             |           |
|--------------------|-----------------------------|-----------------------|--------------------|-------------|-----------|
| <b>Standard</b>    | API Spec 7k<br>API Spec 16C | <b>Equipment type</b> | Borescope<br>MIQAS | <b>S/N:</b> | M22030007 |
| <b>Test Method</b> | Visual Test (Inside Hose)   |                       |                    |             |           |

### Procedure

Check inside for any damage and wear and distortion by using Borescope camera. Visual carried out for the above description and found free of inside defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

None

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

None

|                                      |                                                                                      |                                          |
|--------------------------------------|--------------------------------------------------------------------------------------|------------------------------------------|
| <b>ASNT Level II Inspector Name:</b> | <b>Signature &amp; Stamp:</b>                                                        | <b>Date of Next Through Examination:</b> |
| Abdullah Mofeed                      |  | As Per Client Request                    |

REV: 01 Dated: 20 June 2022

