





## Borescope Examination Report

<b>Client Name:</b>	Daqing Drilling Company	<b>Location:</b>	Rig (DQ 1202)	<b>Job Number:</b>	QC-DQ-04-24-0138
<b>Date of Examination:</b>	03-05-2024	<b>Date of Report:</b>	03-05-2024	<b>Certificate No:</b>	QC-DQ-04-24-0138-31-01
<b>Serial Number</b>	<b>Description of the examined equipment</b>				<b>Result</b>
1026942	ROTARY HOSE				<b>Accepted</b>



### Equipment Details

<b>Standard</b>	API Spec 7k API Spec 16C	<b>Equipment type</b>	Borescope MIQAS	<b>S/N:</b>	M22030007
<b>Test Method</b>	Visual Test (Inside Hose)				

### Procedure

Check inside for any damage and wear and distortion by using Borescope camera. Visual carried out for the above description and found free of inside defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

**None**

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

**None**

<b>ASNT Level II Inspector Name:</b>	<b>Signature &amp; Stamp:</b>	<b>Date of Next Through Examination:</b>
<b>Abdullah Mofeed</b>		<b>As Per Client Request</b>




REV: 01 Dated: 20 June 2022





## Borescope Examination Report

<b>Client Name:</b>	Daqing Drilling Company	<b>Location:</b>	Rig (DQ 1202)	<b>Job Number:</b>	QC-DQ-04-24-0138
<b>Date of Examination:</b>	03-05-2024	<b>Date of Report:</b>	03-05-2024	<b>Certificate No:</b>	QC-DQ-04-24-0138-31-02
<b>Serial Number</b>	<b>Description of the examined equipment</b>				<b>Result</b>
1026942	ROTARY HOSE				<b>Accepted</b>



### Equipment Details

<b>Standard</b>	API Spec 7k API Spec 16C	<b>Equipment type</b>	Borescope MIQAS	<b>S/N:</b>	M22030007
<b>Test Method</b>	Visual Test (Inside Hose)				

### Procedure

Check inside for any damage and wear and distortion by using Borescope camera. Visual carried out for the above description and found free of inside defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

**None**

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

**None**

<b>ASNT Level II Inspector Name:</b>	<b>Signature &amp; Stamp:</b>	<b>Date of Next Through Examination:</b>
<b>Abdullah Mofeed</b>		<b>As Per Client Request</b>




REV: 01 Dated: 20 June 2022





## Borescope Examination Report

<b>Client Name:</b>	Daqing Drilling Company	<b>Location:</b>	Rig (DQ 1202)	<b>Job Number:</b>	QC-DQ-04-24-0138
<b>Date of Examination:</b>	03-05-2024	<b>Date of Report:</b>	03-05-2024	<b>Certificate No:</b>	QC-DQ-04-24-0138-31-03
<b>Serial Number</b>	<b>Description of the examined equipment</b>				<b>Result</b>
2020091444522	MUD PUMP HOSE				<b>Accepted</b>



### Equipment Details

<b>Standard</b>	API Spec 7k API Spec 16C	<b>Equipment type</b>	Borescope MIQAS	<b>S/N:</b>	M22030007
<b>Test Method</b>	Visual Test (Inside Hose)				

### Procedure


Check inside for any damage and wear and distortion by using Borescope camera. Visual carried out for the above description and found free of inside defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

**None**

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

**None**

<b>ASNT Level II Inspector Name:</b>	<b>Signature &amp; Stamp:</b>	<b>Date of Next Through Examination:</b>
<b>Abdullah Mofeed</b>		<b>As Per Client Request</b>

REV: 01 Dated: 20 June 2022








## Borescope Examination Report

<b>Client Name:</b>	Daqing Drilling Company	<b>Location:</b>	Rig (DQ 1202)	<b>Job Number:</b>	QC-DQ-04-24-0138
<b>Date of Examination:</b>	03-05-2024	<b>Date of Report:</b>	03-05-2024	<b>Certificate No:</b>	QC-DQ-04-24-0138-31-04
<b>Serial Number</b>	<b>Description of the examined equipment</b>				<b>Result</b>
2020091444520	MUD PUMP HOSE				<b>Accepted</b>



### Equipment Details

<b>Standard</b>	API Spec 7k API Spec 16C	<b>Equipment type</b>	Borescope MIQAS	<b>S/N:</b>	M22030007
<b>Test Method</b>	Visual Test (Inside Hose)				

### Procedure

Check inside for any damage and wear and distortion by using Borescope camera. Visual carried out for the above description and found free of inside defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

**None**

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

**None**

<b>ASNT Level II Inspector Name:</b>	<b>Signature &amp; Stamp:</b>	<b>Date of Next Through Examination:</b>
<b>Abdullah Mofeed</b>		<b>As Per Client Request</b>


REV: 01 Dated: 20 June 2022





## Borescope Examination Report

<b>Client Name:</b>	Daqing Drilling Company	<b>Location:</b>	Rig (DQ 1202)	<b>Job Number:</b>	QC-DQ-04-24-0138
<b>Date of Examination:</b>	03-05-2024	<b>Date of Report:</b>	03-05-2024	<b>Certificate No:</b>	QC-DQ-04-24-0138-31-05
<b>Serial Number</b>	<b>Description of the examined equipment</b>				<b>Result</b>
2020091444521	MUD PUMP HOSE				<b>Accepted</b>



### Equipment Details

<b>Standard</b>	API Spec 7k API Spec 16C	<b>Equipment type</b>	Borescope MIQAS	<b>S/N:</b>	M22030007
<b>Test Method</b>	Visual Test (Inside Hose)				

### Procedure

Check inside for any damage and wear and distortion by using Borescope camera. Visual carried out for the above description and found free of inside defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

**None**

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

**None**

<b>ASNT Level II Inspector Name:</b>	<b>Signature &amp; Stamp:</b>	<b>Date of Next Through Examination:</b>
<b>Abdullah Mofeed</b>		<b>As Per Client Request</b>

REV: 01 Dated: 20 June 2022










## Borescope Examination Report

<b>Client Name:</b>	Daqing Drilling Company	<b>Location:</b>	Rig (DQ 1202)	<b>Job Number:</b>	QC-DQ-04-24-0138
<b>Date of Examination:</b>	03-05-2024	<b>Date of Report:</b>	03-05-2024	<b>Certificate No:</b>	QC-DQ-04-24-0138-31-06
<b>Serial Number</b>	<b>Description of the examined equipment</b>				<b>Result</b>
2023031140850	CHOCK MANIFOLD HOSE				<b>Accepted</b>



### Equipment Details

<b>Standard</b>	API Spec 7k API Spec 16C	<b>Equipment type</b>	Borescope MIQAS	<b>S/N:</b>	M22030007
<b>Test Method</b>	Visual Test (Inside Hose)				

### Procedure

Check inside for any damage and wear and distortion by using Borescope camera. Visual carried out for the above description and found free of inside defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

**None**

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

**None**

<b>ASNT Level II Inspector Name:</b>	<b>Signature &amp; Stamp:</b>	<b>Date of Next Through Examination:</b>
<b>Abdullah Mofeed</b>		<b>As Per Client Request</b>




REV: 01 Dated: 20 June 2022





## Borescope Examination Report

<b>Client Name:</b>	Daqing Drilling Company	<b>Location:</b>	Rig (DQ 1202)	<b>Job Number:</b>	QC-DQ-04-24-0138
<b>Date of Examination:</b>	03-05-2024	<b>Date of Report:</b>	03-05-2024	<b>Certificate No:</b>	QC-DQ-04-24-0138-31-07
<b>Serial Number</b>	<b>Description of the examined equipment</b>				<b>Result</b>
2023031140846	CHOCK MANIFOLD HOSE				<b>Accepted</b>



### Equipment Details

<b>Standard</b>	API Spec 7k API Spec 16C	<b>Equipment type</b>	Borescope MIQAS	<b>S/N:</b>	M22030007
<b>Test Method</b>	Visual Test (Inside Hose)				

### Procedure

Check inside for any damage and wear and distortion by using Borescope camera. Visual carried out for the above description and found free of inside defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

**None**

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

**None**

<b>ASNT Level II Inspector Name:</b>	<b>Signature &amp; Stamp:</b>	<b>Date of Next Through Examination:</b>
<b>Abdullah Mofeed</b>		<b>As Per Client Request</b>

REV: 01 Dated: 20 June 2022








## Borescope Examination Report

<b>Client Name:</b>	Daqing Drilling Company	<b>Location:</b>	Rig (DQ 1202)	<b>Job Number:</b>	QC-DQ-04-24-0138
<b>Date of Examination:</b>	03-05-2024	<b>Date of Report:</b>	03-05-2024	<b>Certificate No:</b>	QC-DQ-04-24-0138-31-08
<b>Serial Number</b>	<b>Description of the examined equipment</b>				<b>Result</b>
210712-102	CHOCK MANIFOLD HOSE				<b>Accepted</b>



### Equipment Details

<b>Standard</b>	API Spec 7k API Spec 16C	<b>Equipment type</b>	Borescope MIQAS	<b>S/N:</b>	M22030007
<b>Test Method</b>	Visual Test (Inside Hose)				

### Procedure

Check inside for any damage and wear and distortion by using Borescope camera. Visual carried out for the above description and found free of inside defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

**None**

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

**None**

<b>ASNT Level II Inspector Name:</b>	<b>Signature &amp; Stamp:</b>	<b>Date of Next Through Examination:</b>
<b>Abdullah Mofeed</b>		<b>As Per Client Request</b>

REV: 01 Dated: 20 June 2022










## Borescope Examination Report

<b>Client Name:</b>	Daqing Drilling Company	<b>Location:</b>	Rig (DQ 1202)	<b>Job Number:</b>	QC-DQ-04-24-0138
<b>Date of Examination:</b>	03-05-2024	<b>Date of Report:</b>	03-05-2024	<b>Certificate No:</b>	QC-DQ-04-24-0138-31-09
<b>Serial Number</b>	<b>Description of the examined equipment</b>				<b>Result</b>
210106-101	CHOCK MANIFOLD HOSE				<b>Accepted</b>



### Equipment Details

<b>Standard</b>	API Spec 7k API Spec 16C	<b>Equipment type</b>	Borescope MIQAS	<b>S/N:</b>	M22030007
<b>Test Method</b>	Visual Test (Inside Hose)				

### Procedure

Check inside for any damage and wear and distortion by using Borescope camera. Visual carried out for the above description and found free of inside defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

**None**

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

**None**

<b>ASNT Level II Inspector Name:</b>	<b>Signature &amp; Stamp:</b>	<b>Date of Next Through Examination:</b>
<b>Abdullah Mofeed</b>		<b>As Per Client Request</b>



REV: 01 Dated: 20 June 2022





## Borescope Examination Report

<b>Client Name:</b>	Daqing Drilling Company	<b>Location:</b>	Rig (DQ 1202)	<b>Job Number:</b>	QC-DQ-04-24-0138
<b>Date of Examination:</b>	03-05-2024	<b>Date of Report:</b>	03-05-2024	<b>Certificate No:</b>	QC-DQ-04-24-0138-31-10
<b>Serial Number</b>	<b>Description of the examined equipment</b>				<b>Result</b>
514525	KILL LINE HOSE				<b>Accepted</b>



### Equipment Details

<b>Standard</b>	API Spec 7k API Spec 16C	<b>Equipment type</b>	Borescope MIQAS	<b>S/N:</b>	M22030007
<b>Test Method</b>	Visual Test (Inside Hose)				

### Procedure

Check inside for any damage and wear and distortion by using Borescope camera. Visual carried out for the above description and found free of inside defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

**None**

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

**None**

<b>ASNT Level II Inspector Name:</b>	<b>Signature &amp; Stamp:</b>	<b>Date of Next Through Examination:</b>
<b>Abdullah Mofeed</b>		<b>As Per Client Request</b>

REV: 01 Dated: 20 June 2022









## Borescope Examination Report

<b>Client Name:</b>	Daqing Drilling Company	<b>Location:</b>	Rig (DQ 1202)	<b>Job Number:</b>	QC-DQ-04-24-0138
<b>Date of Examination:</b>	03-05-2024	<b>Date of Report:</b>	03-05-2024	<b>Certificate No:</b>	QC-DQ-04-24-0138-31-11
<b>Serial Number</b>	<b>Description of the examined equipment</b>				<b>Result</b>
514469	KILL LINE HOSE				<b>Accepted</b>



### Equipment Details

<b>Standard</b>	API Spec 7k API Spec 16C	<b>Equipment type</b>	Borescope MIQAS	<b>S/N:</b>	M22030007
<b>Test Method</b>	Visual Test (Inside Hose)				

### Procedure

Check inside for any damage and wear and distortion by using Borescope camera. Visual carried out for the above description and found free of inside defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

**None**

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

**None**

<b>ASNT Level II Inspector Name:</b>	<b>Signature &amp; Stamp:</b>	<b>Date of Next Through Examination:</b>
<b>Abdullah Mofeed</b>		<b>As Per Client Request</b>

REV: 01 Dated: 20 June 2022

