



LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATE NO:	QC-SLB-25179-17	
LOCATION:	SLICKLINE WORKSHOP			
EXAMINATION DATE:	08/Jul/2025	JOB NO:	QC-SLB-25179	
LAST INSPECTION		NEXT INSPECTION DATE		PROOF LOAD TEST DATE
12/Jan/2025		07/Jan/2026		By Manufacture
IDENTIFICATION NO	DESCRIPTION			QTY
1406051	<p><u>DRUM CLAMP INTEGRATED WITH 2 LEG CHAIN</u></p> <p>CHAIN SIZE: 6mm LENGTH: 500 mm EQUIPPED WITH: TWO CLAMP LOWER TERMINATION SPREADER CLAMP LINK UPPER TERMINATION.</p> 			01
SWL	1 TON			
Applicable Reference Standard:	BS EN 818-2:1996+A1:2008		UNIT #03	
* Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES	NO	√	
	* Within an interval of 6 months?		YES	√
	* Within an interval of 12 months?		YES	√
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	√	
	* By an examination scheme?		YES	√
* After the occurrence of exceptional circumstances?		YES	√	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None				
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES	NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None				
** Visual And Dimension Check was Carried Out.				
Is This Equipment Safe To Operate?		Yes Accept	√	NO Reject

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohammad Abdullah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

