Al TAKAMUL COMPANY FOR ENGINEERING TESTS
AND PROFESSIONAL SAFETY LIMITED
Basra, North Rumaila, Quality Control Yard - Iraq
Tel: +9647810009138 / +9647834964657
Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com

CERTIFICATE OF INSPECTION AFTER REPAIR FOR 9" DRILL COLLAR

Client Name:	**DAQING DRILLING**	Report No.:	DQ-37-QC-24-07-NA.006
Acceptance Createra.	☑API SPEC 7-2	Date of Inspection:	11.JULY.2024
Work Location:	**ABERDEEN WORKSHOP**	Rig No.:	DQ-37
Test Equipment & Consumeable Details			
WHITE CONTRAST WCP-2	Batch #: 220602 Manufacture: Magnaflux Exp Date: JUN,2025	TECHNICAL DETAILS	Wet Visible Continuous
BLACK INK 7HF	Batch#.220605 Manufacture: Magnaflux Exp Date: JULY.2025	COIL(1200 AMP-TURNS/IN	22713 Cal.15.FEB.2024 Cal Due14.OCT.2024
FLUORESCENT 14HF	Batch #: 220306 Manufacture: Magnaflux Exp Date: March.2025	A.C HAND YOKE	PY-10 Cal.15.FEB.2024 Cal Due14.OCT.2024
INTENSITY METER	SR#1608000134 CAL.Date .15.FEB.2024 Cal Due14.OCT.2024	UV BLACK LIGHT	SR#1946875 Cal.15.FEB.2024 Cal Due14.OCT.2024
LEAD GAGE	SR#AH07KF0027 GAEMAKER LG-5003 Cal.15.FEB.2024 Cal Due14.OCT.2024	THREAD PROFILE GAGE	SR#21336 Cal. Cal.15.FEB.2024 Cal Due14.OCT.2024 SR#21335 Cal. Cal.15.FEB.2024 Cal Due14.OCT.2024
Magnetic Partical Concentration 7 HF	1.2 TO 2.4 ML/100 ML	WMPT Light Intensity	3500 Lux
Magnetic particle concentration flourcent 14 HF	0.1 TO 0.4 ML/100 ML	UV LIGHT INTENSITY:	3050 µw/cm²
Magnetism Direction (Longitudinal)			
METHODOLOGY:	• Through Visual inspection • Dimensional	•MPI inspection with Ultraviolet light *Lead Gaiging, Taper Gauging & Thread Profile Gauging.	
Connection:	**7 5/8 REG**	**Size:**	**9"**

Serial No.	Visual Inspection			MPI			Dimensional 3 Inspection																	
							Pin						Box						Body					
	Pin	Box	Body	Pin	Box	Body	OD (in)	ID (in)	SRG ☐ (in)	SRG W ☐ (in)	Pin ☐ (in)	Bevel ☐ (in)	OD (in)	CBD ☐ (in)	CBW ☐ (in)	BB ☐ (in)	BBL ☐ (in)	Bevel ☐ (in)	Pin Tong ☐ (in)	Box Tong ☐ (in)	EGR ☐ (in)	SGR ☐ (in)	Overall ☐☐ (In)	
57948-71	Acc.	--	--	Acc.	--	---	9"	3 1/16"	6 13/32"	7/8"	5 ¼"	8 ¾"	---	---	---	---	--	--	21 7/8"	--	-	--	--	
Conclusion:	■ (01)The above Mentioned 9" Drill Collar were found "Acceptable" from Pin Connection After Repair at time of Inspection ready to use.																							

Abbreviations :

OD	*Outside Diameter*	**ID**	*Inside Diameter*	**SRG**	*Stress Relief Groove*	**CB**	*Counter Bore*	**BB**	*Bore Back*	**FB**	*Float Bore*
☐	*Diameter*	☐	*Length*	☐	*Width*	☐	*Depth*	***NP.***	*Not Present*	***NA.***	*Not Applicable*
EGR	*Elevator Groove Recess*	**SGR**	*Slip Groove Recess*	**CR**	*Crack*	**B**	*Bent*	**PC**	*Premium Class*	**RF**	*Reface*
GT	*Galled Thread*	**PT**	*Pitting Thread*	**SP**	*Seal Pitting*	**TD**	*Thread Damage*	**SD**	*Seal Damage*	**M**	*Mashed*
1	*100 % Coating*	**2**	*99-71 % Coating*	**3**	*70-40 % Coating*	**4**	*Up to 40 %*	**5**	*Nil*	**WT**	*Wall Thickness*

Colors Code: ***White*** - **No Defects** | *Red* - **Crack or Extreme Damage.** | **Blue** - **Damage** | **Green** - **Seal Damage** | **Yellow** - **ACFM**

Inspector Name:	[illegible]	**Review By**			
Qualification:	ASNT Level II	**Senior Inspector:**	M. SARWAR	**Supervisor:**	RAO SOHAIL
Signature:				**Customer Name:**	
				Customer Signature:	