Al TAKAMUL COMPANY FOR ENGINEERING TESTS
AND PROFESSIONAL SAFETY LIMITED
Basra, North Rumaila, Quality Control Yard - Iraq

LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	**SLB BASRA**	**CERTIFICATE NO:**	**QC-SLB-25180-11**	
LOCATION:	**WIRELINE WORKSHOP**			
EXAMINATION DATE:	**10/Jul/2025**	**JOB NO:**	**QC-SLB-25180**	

LAST INSPECTION	NEXT INSPECTION DATE	LAST PROOF LOAD TEST DATE
14/Jan/2025	09/Jan/2026	BY MANUFACTURE

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
BLP-265712-047	**DOUBLE HOOK CHAIN-FOR LOGIN UNIT RIG UP** Diameter: 7 mm X 0.60 m SIZE: 9/32'' X 23" IN Grade: 100 Safety Latch Hook at the End SAFETY FACTOR 4:1 	01	12000 LBS

Applicable Reference Standard:	BS EN 818-2:1996+A1:2008							
* Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?			
					* Within an interval of 6 months?	YES	√	NO	
					* Within an interval of 12 months?	YES		NO	√
* If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		* By an examination scheme?	YES	√	NO	
					* After the occurrence of exceptional circumstances?	YES		NO	√

Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None						
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES		NO	√
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)	NO	√	YES		By:	
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None						
** Visual And Dimension Check was Carried Out.						
Is This Equipment Safe To Operate?	Yes Accept	√	NO Reject			

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohammed Abdallah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT; a comp[illegible]ove-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.