Al TAKAMUL COMPANY FOR ENGINEERING TESTS
AND PROFESSIONAL SAFETY LIMITED
Basra, North Rumaila, Quality Control Yard - Iraq

LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	**SLB BASRA**	**CERTIFICATION NO:**	**QC-SLB-25215-18**	
LOCATION:	**WIRE LINE SPOOLING AREA**			
EXAMINATION DATE:	**21/Aug/2025**	**JOB NO:**	**QC-SLB-25215**	

LAST INSPECTION	NEXT INSPECTION DATE	PROOF LOAD TEST DATE
21/Feb/2025	20/Feb/2026	BY MANUFACTURE

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
F3976 F3975	**Single Leg Wire Rope Sling.** **Diameter: 8mm** **Length: 1.5 m** **IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE** **HARD EYE ON BOTH ENDS.** **SAFETY FACTOR 5:1** 	02	1.55 Ton

Applicable Reference Standard:	**BS EN 13414-1:2003+A2:2008**							
*** Is this the first examination after installation or assembly at a new site or location?**	YES		NO	√	**Was the examination carried out?**				
					*** Within an interval of 6 months?**	YES	√	NO	
					*** Within an interval of 12 months?**	YES		NO	√
*** If the answer to the above question is YES has the equipment been installed correctly?**	YES	√	NO		*** By an examination scheme?**	YES	√	NO	
					*** After the occurrence of exceptional circumstances?**	YES		NO	√

Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: **None**

Is The Above A Defect Which Is Of Immediate Danger To Persons			**YES**		**NO**	√
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)	**NO**	√	**YES**		**By:**	

Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: **None**

**** Visual And Dimension Check was Carried Out.**

Is This Equipment Safe To Operate?	**Yes Accept**	√	**NO Reject**	

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohemmad Abdullah		**Ashraf Alsaad**	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.