

# DEFECT REPORT

CERTIFICATION NO:	QC-HH-04-24-0130	LOCATION:	HH Rig 029	具数数
JOB NO:	QC-HH-04-24-0130-01D	LOCATION.	1111 Kig 029	
CLIENT:	Hong Hua Oil& Gas Engineering Services Ltd	DATE:	19.04.2024	

Item No.	Serial No.	Description	Defect	Rejected as per standard
01	B3112	SINGLE LEG WIRE ROPE SLINGE	Cutting in the Ferrule	Not safe to use and must be
		19 mm Diameter, 120 M Length,	specifications standard	replaced
		FERRULE. Hard Eye X Plain.	Visual Inspection Not Accepted	
02	98895-8/9	Webbing Sling Length: 10 M SWL: 5 TON Safety Factor: 7:1 Color: Red	Cutting in the Body specifications standard Visual Inspection Not Accepted	Not safe to use and must be replaced
03	96271-14/13	Webbing Sling Length: 10 M SWL: 10 TON Safety Factor: 7:1 Color: Red	Cutting in the Body specifications standard Visual Inspection Not Accepted	Not safe to use and must be replaced

# PICTURE 1





Name of Inspector:	Name of person authenticating this report:	Signature & Stamp:
Mahmoud Ali	Mohamed Abdalla	



CERTIFICATION NO:	QC-HH-04-24-0130	LOCATION:	HH Rig 029	
JOB NO:	QC-HH-04-24-0130-01D			
CLIENT:	Hong Hua Oil& Gas Engineering Services Ltd	DATE:	19.04.2024	


## PICTURE 2





### PICTURE 3





Name of Inspector:	Name of person authenticating this report:	Signature & Stamp:
Mahmoud Ali	Mohamed Abdalla	