

## **CERTIFICATE OF THOROUGH EXAMINATION**

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	16/05/2024		Date of Report:	Date of Report: 16/05/202			Certificate No:		QC-24-WPS-1605-011		
Client Name:	HALI	LIBURTON	Location:		WPS		Job Number:		160524		
Serial Number:	QTY		Description				Date of manufacture if known:	Date of last thorough examination			
HST-043167-008	1	GRADE: 8 SIZE: 1 1/			18 T		N/A	12/11/2023			
Reference Standard:         BS EN 13889/ HAL DOC: ST-GL-HAL-HSE-0420											
Is this the first examination after Installation or assembly at a new site or locat If the answer to the above question is YES has equipment been installed correctly? Identification of any part found to have a defe			ne YES NO	After the occurrence circumstances?			<ul> <li><sup>6</sup> 6 months?</li> <li><sup>2</sup> months?</li> <li><sup>4</sup> Y</li> <li><sup>4</sup> n examination scheme?</li> <li><sup>4</sup> Y</li> <li><sup>4</sup> of exceptional</li> <li><sup>4</sup> Y</li> </ul>		ES √ ES √ ES ct: (If n	NO NO NO NO	√ √
NONE) NONE											
Is the above a defect which Is the above a defect which (If YES state the date by whe Particulars of any repair, rer	et but could		tified above	N/A					V		
Particulars of any tests carri The subject Items were insp satisfactory IS THIS EQUIPMENT SAFE TO	ed out a ected V	as part of the isually and d	e examination: (If none st	ate NONE	)			ection (ES	and fou	ind NO	
Name of Inspector:			Name of person authenticating this report:			Client Signature & Stamp:					
ASHRAF ELSAID			MOHAMED ABDALLAH			ALI Talib HB48903 Date: 17/05/2024					
Date of Next Through Ex	tion:	15/11/2024			Signature Haliburton						
REV: 01 Dated: 20 June 2022		EC	LE								

THIS IS TO CERTIFY THAT; a competed e above-mentioned owner's work location on the date shown above and the 1 124 & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation equipment described in this report wa "LOLER". The result was found Satisfactory at the time of the pection and considered Safe for Lifting.

