

LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATE NO:	QC-SLB/25181-03
LOCATION:	WIRE LINE WORKSHOP	JOB NO:	QC-SLB/25181
EXAMINATION DATE:	12/Jul/2025		
LAST INSPECTION	NEXT INSPECTION DATE	LAST PROOF LOAD TEST DATE	
14/Jan/2025	11/Jan/2026	15/JUN/2023	
IDENTIFICATION NO	DESCRIPTION	QTY	SWL
NE3896	<u>Four Leg Wire Rope Sling.</u> Diameter: 13 mm Length: 4 ft IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE C/W MASTER LINK ASSEMBLY AT TOP HARD EYE AT BOTH END SAFETY FACTOR 5:1 	01	4.2 TON @0-45°
Applicable Reference Standard:	BS EN 13414-1:2003+A2:2008 UNIT#049		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	✓
	Was the examination carried out?		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	✓	NO
	* Within an interval of 6 months?		
	YES	✓	NO
	* Within an interval of 12 months?		
	YES	✓	NO
	* In accordance with an examination scheme?		
	YES	✓	NO
	* After the occurrence of exceptional circumstances?		
	YES	✓	NO
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES	NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)		NO	✓
Particulars Of Any Repair, Renewal Or Alteration Required To Remedy The Defect Identified Above:		YES	By:
		✓	
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?	Yes Accept	✓	NO Reject

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohammad Abdullah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

