


LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATE NO:	QC-SLB-25172-05	
LOCATION:	WIRELINE WORKSHOP			
EXAMINATION DATE:	28/Jun/2025			
LAST INSPECTION		NEXT INSPECTION DATE		LAST PROOF LOAD TEST DATE
14/Jan/2025		27/Dec/2025		BY MANUFACTURE
IDENTIFICATION NO	DESCRIPTION			QTY
BLP-265712-047	DOUBLE HOOK CHAIN-FOR LOGIN UNIT RIG UP Diameter: 7 mm X 0.60 m SIZE: 9/32" X 23" IN Grade: 100 Safety Latch Hook at the End SAFETY FACTOR 4:1 TRUK NO:5898			01
				
Applicable Reference Standard:		BS EN 818-2:1996+A1:2008		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	Was the examination carried out?	
		✓	* Within an interval of 6 months? YES ✓ NO * Within an interval of 12 months? YES NO ✓	
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	* By an examination scheme? YES ✓ NO	
	✓		* After the occurrence of exceptional circumstances? YES NO ✓	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None				
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES	NO ✓
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO ✓	YES By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None				
** Visual And Dimension Check was Carried Out.				
Is This Equipment Safe To Operate?		Yes Accept	✓	NO Reject

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohammed Abdallah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT; a complete thorough examination of the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

