

LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATE NO:	QC-SLB-25206-10A
LOCATION:	WIRE LINE WORKSHOP	JOB NO:	QC-SLB-25206
EXAMINATION DATE:	8/Aug/2025		
LAST INSPECTION	NEXT INSPECTION DATE	LAST PROOF LOAD TEST DATE	
24/Feb/2025	7/Feb/2026	BY MANUFACTURE	
IDENTIFICATION NO	DESCRIPTION	QTY	SWL
L-690706-001	<u>SPREADER PLATE</u> Triangular Spreader Plate with Single Lifting Point On Top and Three Lifting Point at The Bottom, Constructed of Welded Steel Plates. SPAN: 0.54 m	01	TOP CENTER 9 TON BOTTOM CENTER 6 TON BOTH SIDE 1.5 TON
Applicable Reference Standard:	BS EN 13155 :2003+A2:2009 UNIT 042		
* Is this the first examination after installation or assembly at a new site or location? * If the answer to the above question is YES has the equipment been installed correctly?	Was the examination carried out?		
	YES	NO	✓
	* Within an interval of 6 months? YES ✓ NO * Within an interval of 12 months? YES NO ✓		
	* By an examination scheme? YES ✓ NO * After the occurrence of exceptional circumstances? YES NO ✓		
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES	NO ✓
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)		NO ✓	YES By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept ✓	NO Reject

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohamed Abdallah		ASHRAF ELSAAD	

THIS IS TO CERTIFY THAT; a competent person has examined the re-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

