

LIFTING ACCESSORIES CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

CLIENT:	SLB BASRA	CERTIFICATE NO:	QC-SLB-25245-86
LOCATION:	ARTIFICIAL LIFT		
EXAMINATION DATE:	25/Sep/2025	JOB NO:	QC-SLB-25245
LAST INSPECTION	NEXT INSPECTION DATE	LAST PROOF LOAD TEST DATE	
24/Feb/2025	24/Mar/2026	BY MANUFACTURE	
IDENTIFICATION NO	DESCRIPTION	QTY	SWL
SC8988 SC8997	<u>LIFTING CLAMP ASSEMBLY</u> Lifting Clamp Assembly, Into Two Halves Bolted Together Complete of Two Lifting Points One On Each Side. Constructed of Welded Steel Plates. Manufacture: SCIMEX PRECISION ENGINEERING	02	18000 LBS
Applicable Reference Standard:	BS EN 13155		
* Is this the first examination after installation or assembly at a new site or location?	YES ☐ NO ☒	Was the examination carried out?	
* If the answer to the above question is YES has the equipment been installed correctly?	YES ☒ NO ☐	* Within an interval of 6 months? YES ☒ NO ☐ * Within an interval of 12 months? YES ☐ NO ☒ * By an examination scheme? YES ☒ NO ☐ * After the occurrence of exceptional circumstances? YES ☐ NO ☒	
Identification of Any Part Found to Have a Defect Which Is or Could Become a Danger to Persons and A Description of the Defect: None			
Is The Above a Defect Which Is of Immediate Danger to Persons		YES ☐	NO ☒
Is The Above a Defect Which Is Not Yet but Could Become a Danger to Persons: (If YES State The Date By When)		NO ☒	YES ☐ By: _____
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual and Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?	Yes Accept ☒	NO Reject ☐	

INSPECTOR	SIGNATURE:	SUPERVISOR:	SIGNATURE:
Mohammed Abdullah		Ashraf Elsaad	

THIS IS TO CERTIFY THAT; a competent person and agent of the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

