



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	06-02-2025	Date of Report:	06-02-2025	Certificate No:	QC-IBC-01-25-0110/01
Client Name:	IBC Co.	Location:	QC Yard	Job Number:	QC-IBC-01-25-0110
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
CS03 CS04	02	CHAIN SLING Two Leg Chain Sling 16 mm Dia (Grade 8), 8 M Length, C/W Master Link Assembly on Top End with Shorting Clutches on Two Leg Termination with Clevis Self Locking Hook Safety Factor: 4:1	11.2 T @ (0-45) DEG	N/A	02-07-2024
Reference Standard:	BS EN 818-4:1996 + A1:2008				
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		Was the examination carried out:	
				Within an interval of 6 months?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> ✓ <input type="checkbox"/> NO <input type="checkbox"/> ✓	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> ✓		Within an interval of 12 months?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> ✓ <input type="checkbox"/> NO <input type="checkbox"/> ✓	
				In accordance with an examination scheme?	
				<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect which is of immediate danger to persons:				YES	<input type="checkbox"/>
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				NO	<input checked="" type="checkbox"/> ✓
Particulars of any repair, renewal or alteration required to remedy the defect identified above:				YES by:	
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				YES	<input checked="" type="checkbox"/> ✓
				NO	<input type="checkbox"/>
Name of Inspector:	Name of person authenticating this report:	Signature of person:			
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	05-08-2025				

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

