



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Aberdeen Technical Service Company	Certificate no:	QC-B-01-25-0035/01
Location:	Aberdeen Yard	Job Order No.:	QC-B-01-25-0035
Date of Examination:	25-Jan-2025	Next Inspection Due:	24-July-2025
Last Inspection		Last Proof Load Test Date	
07/08/2024		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
D2170238 D2170235 D2170249	Flat Woven Webbing Sling C/W Folded Soft Eye at Each End Double Ply Material: 100% Polyester (PET) Manufacturer: Webblon Korea Date of Manufacture: 14/02/2017 Factor of Safety: 7:1 Color: Green Width: 2" Length: 5 m	03	2t Vertical 4t Basket 1.6t Choker
Reference Standard:	BS EN 1492-1:2000+A1:2008		

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out: Within 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?	YES	√	NO			
						YES		NO	√		
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO			YES	√	NO			
						YES		NO	√		
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE											
Is the above a defect which is of immediate danger to persons:								YES		NO	√
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)						N/A					
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:											
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory											
IS THIS EQUIPMENT SAFE TO OPERATE?								YES	√	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Mohamed Abdulla		Ashraf ElSaid	

THIS IS TO CERTIFY THAT: a competent person attended the owner mentioner's work location on the date shown above and the Equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Aberdeen Technical Service Company	Certificate no:	QC-B-01-25-0035/02
Location:	Aberdeen Yard	Job Order No.:	QC-B-01-25-0035
Date of Examination:	25-Jan-2025	Next Inspection Due:	24-July-2025
Last Inspection		Last Proof Load Test Date	
07/08/2024		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
D5170206	<p>Flat Woven Webbing Sling</p> <p>C/W Folded Soft Eye at Each End Double Ply Material: 100% Polyester (PET) Manufacturer: Webblon Korea Date of Manufacture: 14/02/2017 Factor of Safety: 7:1 Color: Red Width: 5" Length: 2 m</p>	01	5t Vertical 10t Basket 4t Choker
Reference Standard:	BS EN 1492-1:2000+A1:2008		

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out: Within 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?	YES	√	NO			
						YES		NO	√		
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO			YES	√	NO			
						YES		NO	√		
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE											
Is the above a defect which is of immediate danger to persons:								YES		NO	√
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)						N/A					
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:											
Particulars of any tests carried out as part of the examination: (If none state NONE) <i>The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory</i>											
IS THIS EQUIPMENT SAFE TO OPERATE?								YES	√	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Mohamed Abdulla		Ashraf ElSaid	

THIS IS TO CERTIFY THAT: a competent person attended the owner mentioner's work location on the date shown above and the Equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Aberdeen Technical Service Company	Certificate no:	QC-B-01-25-0035/03
Location:	Aberdeen Yard	Job Order No.:	QC-B-01-25-0035
Date of Examination:	25-Jan-2025	Next Inspection Due:	24-July-2025
Last Inspection		Last Proof Load Test Date	
20/07/2024		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
96962-52/7 96962-52/6	Flat Woven Webbing Sling C/W Folded Soft Eye at Each End Double Ply Material: 100% Polyester (PET) Manufacturer: LIFTEK Date of Manufacture: 14/02/2017 Factor of Safety: 7:1 Color: Orange Width: 10" Length: 12 m	02	10 t Vertical 20 t Basket 8 t Choker

Reference Standard: BS EN 1492-1:2000+A1:2008

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	✓	Was the examination carried out: Within 6 months?	YES	✓	NO			
						With an interval of 12 months?	YES		NO	✓	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		By an examination scheme?	YES	✓	NO			
					After the occurrence of exceptional circumstances?	YES		NO	✓		
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE											
Is the above a defect which is of immediate danger to persons:								YES		NO	✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)						N/A					
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:											
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory											
IS THIS EQUIPMENT SAFE TO OPERATE?								YES	✓	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Mohamed Abdulla		Ashraf ElSaid	

THIS IS TO CERTIFY THAT: a competent person attended the owner mentioner's work location on the date shown above and the Equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.