

**AI TAKAMUL COMPANY FOR ENGINEERING TESTS  
AND PROFESSIONAL SAFETY LIMITED**

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: [OP@qualitycontrol-iraq.com](mailto:OP@qualitycontrol-iraq.com) / [hany.akafi@qualitycontrol-iraq.com](mailto:hany.akafi@qualitycontrol-iraq.com)




**CERTIFICATE OF THOROUGH EXAMINATION**

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

|   |   |  |  |                                      |   |
|---|---|--|--|--------------------------------------|---|
| <b>Date of Examination:</b>   | 11/01/2025  | <b>Date of Report:</b>   | 11/01/2025   | <b>Certificate No:</b>               | QC-25/-WPS-1101-11  |
| <b>Client Name:</b>   | HALLIBURTON                                       | <b>Location:</b>   | WPS  | <b>Job Number:</b>                   | 110125  |
| <b>Serial Number:</b>   | QTY   | <b>Description</b>   | <b>SWL</b>   | <b>Date of manufacture if known:</b> | <b>Date of last thorough examination</b>                            |
| MM2   | 01  | <p align="center"><b><u>SAFETY PIN BOW SHACKLE</u></b></p> <p><b>MANUFACTURER:</b> CROSBY</p> <p><b>SIZE:</b> 1 1/8"</p> <p><b>GRADE:</b> 6</p> <p><b>FOS:</b> 6:1</p> | 9.5 TON  | N/A                                  | 24/06/2024  |
| <b>Reference Standard:</b>  | BS EN 13889/ HAL DOC: ST-GL-HAL-HSE-0420          |  |  |                                      |   |
| Is this the first examination after Installation or assembly at a new site or location?   |   | YES  | NO   | √                                    | Was the examination carried out:<br>Within an interval of 6 months? |
|   |   |  |  |                                      | YES   |
|   |   |  |  |                                      | With an interval of 12 months?                                      |
|   |   |  |  |                                      | YES   |
| If the answer to the above question is YES has the equipment been installed correctly?  |   | YES  | NO   |                                      | In accordance with an examination scheme?                           |
|   |   |  |  |                                      | YES   |
|   |   |  |  |                                      | After the occurrence of exceptional circumstances?                  |
|   |   |  |  |                                      | YES   |
| Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE |   |  |  |                                      |   |
| Is the above a defect which is of immediate danger to persons:  |   |  |  |                                      | YES   |
| Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)   |   |  |  |                                      | N/A   |
| Particulars of any repair, renewal or alteration required to remedy the defect identified above:  |   |  |  |                                      |   |
| Particulars of any tests carried out as part of the examination: (If none state NONE)   |   |  |  |                                      |   |
| The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory          |   |  |  |                                      |   |
| <b>IS THIS EQUIPMENT SAFE TO OPERATE?</b>   |   |  |  |                                      | YES   |
|   |   |  |  |                                      | √   |
|   |   |  |  |                                      | NO  |
|   |   |  |  |                                      | √   |
| <b>Name of Inspector:</b>   | <b>Name of person authenticating this report:</b> |  | <b>Client Signature &amp; Stamp:</b>   |                                      |   |
| ASHRAF ELSAID   | MOHAMED ABDALLAH                                  |  | <b>ALI Talib HB48903</b><br><b>Date: 12/01/2025</b><br><b>Signature</b><br><b>Haliburton</b> |                                      |   |
| <b>Date of Next Through Examination:</b>  | 10/07/2025  |  |  |                                      |   |

REV: 01 Dated: 20 June 2022



**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of inspection and considered Safe for Lifting.

