



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Hong Hua Oil& Gas Engineering Services Ltd	Certificate no:	QCQC-HH-02-25-050/02/01
Location:	HH Rig 008	Job Order No:	QCQC-HH-02-25-050
Date of Examination:	20-Mar-2025	Next Inspection Due:	19-SEP-2025
Last Inspection		Last Proof Load Test Date	
New		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
P3 P4 P5	<p align="center"><u>EYE BOLT</u></p> Type: CS15 Collar Eye Bolt Material: Forged Steel Eye Bolt Thread Dia: 20 mm Thread Ident: M20 Safety Factor: 5:1	03	1.2 Ton
Reference Standard:	BS EN ISO 3266:2010+A1:2015		

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	v	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?	YES	v	NO			
						YES		NO	v		
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO			YES	v	NO			
						YES		NO	v		
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE											
Is the above a defect which is of immediate danger to persons:								YES		NO	v
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)						N/A					
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:											
Particulars of any tests carried out as part of the examination: (If none state NONE) <i>Visual And Dimension Check was Carried Out.</i>											
IS THIS EQUIPMENT SAFE TO OPERATE?								YES	v	NO	

LEEA & ASNT Level II Inspector Name:		Authenticating This Report:	Signature:
Mahmoud Ali Khaled Mahmoud		Ashraf El Said	

THIS IS TO CERTIFY THAT: a competent person did attend the owner mentioner's work location on the date shown above and the Equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Hong Hua Oil& Gas Engineering Services Ltd	Certificate no:	QCQC-HH-02-25-050/02/02
Location:	HH Rig 008	Job Order No:	QCQC-HH-02-25-050
Date of Examination:	20-Mar-2025	Next Inspection Due:	19-SEP-2025
Last Inspection		Last Proof Load Test Date	
New		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
P1	<p align="center"><u>EYE BOLT</u></p> Type: HW14 Collar Eye Bolt Material: Forged Steel Eye Bolt Thread Dia: 20 mm Thread Ident: M20 Safety Factor: 5:1	01	1.6 Ton
Reference Standard:	BS EN ISO 3266:2010+A1:2015		

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	v	Was the examination carried out: Within an interval of 6 months?	YES	v	NO			
						With an interval of 12 months?	YES		NO	v	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		By an examination scheme?	YES	v	NO			
					After the occurrence of exceptional circumstances?	YES		NO	v		
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE											
Is the above a defect which is of immediate danger to persons:								YES		NO	v
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)						N/A					
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:											
Particulars of any tests carried out as part of the examination: (If none state NONE) <i>Visual And Dimension Check was Carried Out.</i>											
IS THIS EQUIPMENT SAFE TO OPERATE?								YES	v	NO	

LEEA & ASNT Level II Inspector Name:		Authenticating This Report:	Signature:
Mahmoud Ali Khaled Mahmoud		Ashraf El Said	

THIS IS TO CERTIFY THAT: a competent person did attend the owner mentioner's work location on the date shown above and the Equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.