



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Hong Hua Oil& Gas Engineering Services Ltd	Certificate no:	QCQC-HH-02-25-050/01
Location:	HH Rig 008	Job Order No:	QCQC-HH-02-25-050
Date of Examination:	20-Mar-2025	Next Inspection Due:	19-SEP-2025
Last Inspection New		Last Proof Load Test Date By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
95886-1/23 95886-1/9	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: LIFTEK Date of Manufacture: 23/11/2022 Material: 100% PES, Colour: BLUE Length: 10 m Width: 8” Safety Factor: 7:1	02	8000 KG Vertical 6400 KG Choker 16000 KG Basket



Reference Standard:	BS EN 1492-1:2000-A1:2008
---------------------	---------------------------

Is this the first examination after Installation or assembly at a new site or location? If the answer to the above question is YES has the equipment been installed correctly?	YES <input type="checkbox"/> NO <input type="checkbox"/> v <input type="checkbox"/>	Was the examination carried out: Within an interval of 6 months? Within an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?	YES <input type="checkbox"/> v <input type="checkbox"/> NO <input type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> v YES <input type="checkbox"/> v <input type="checkbox"/> NO <input type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> v
---	---	--	--

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) **NONE**

Is the above a defect which is of immediate danger to persons: YES NO v


Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal, or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: (If none state NONE)
 Visual And Dimension Check was Carried Out.

IS THIS EQUIPMENT SAFE TO OPERATE? YES v NO

LEEA & ASNT Level II Inspector Name: Mahmoud Ali Khaled Mahmoud	Authenticating This Report: Ashraf El Said	Signature:
---	---	------------



THIS IS TO CERTIFY THAT: a competent person did attend the owner mentioner’s work location on the date shown above and the Equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.





Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Hong Hua Oil& Gas Engineering Services Ltd	Certificate no:	QCQC-HH-02-25-050/02
Location:	HH Rig 008	Job Order No:	QCQC-HH-02-25-050
Date of Examination:	20-Mar-2025	Next Inspection Due:	19-SEP-2025
Last Inspection New		Last Proof Load Test Date By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
91433-5/6	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: LIFTEK Date of Manufacture: 17/11/2021 Material: 100% PES, Colour: ORANGE Length: 10 m Width: 10" Safety Factor: 7:1	01	15000 KG Vertical 12000 KG Choker 30000 KG Basket



Reference Standard: BS EN 1492-1:2000-A1:2008

Is this the first examination after Installation or assembly at a new site or location?	YES	NO	v	Was the examination carried out: Within an interval of 6 months?	YES	v	NO	
					Within an interval of 12 months?	YES		NO
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO		By an examination scheme?	YES	v	NO	
				After the occurrence of exceptional circumstances?	YES		NO	v

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) **NONE**


Is the above a defect which is of immediate danger to persons: YES NO v

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal, or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: (If none state NONE)
 Visual And Dimension Check was Carried Out.

IS THIS EQUIPMENT SAFE TO OPERATE? YES v NO

LEEA & ASNT Level II Inspector Name:		Authenticating This Report:	Signature:
Mahmoud Ali Khaled Mahmoud		Ashraf El Said	

THIS IS TO CERTIFY THAT: a competent person did attend the owner mentioner's work location on the date shown above and the Equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.






Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Hong Hua Oil& Gas Engineering Services Ltd	Certificate no:	QCQC-HH-02-25-050/03
Location:	HH Rig 008	Job Order No:	QCQC-HH-02-25-050
Date of Examination:	20-Mar-2025	Next Inspection Due:	19-SEP-2025
Last Inspection New		Last Proof Load Test Date By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
1322	<p>Flat Woven Webbing Sling</p> <p>Double Ply Folded Eye at both ends</p> <p>Manufacturer: SAFETY MARINE</p> <p>Date of Manufacture: 7/2019</p> <p>Material: 100% PES,</p> <p>Colour: BLUE</p> <p>Length: 10 m</p> <p>Width: 8"</p> <p>Safety Factor: 7:1</p> 	01	<p>8000 KG Vertical</p> <p>6400 KG Choker</p> <p>16000 KG Basket</p>

Reference Standard:	BS EN 1492-1:2000-A1:2008
---------------------	---------------------------

Is this the first examination after Installation or assembly at a new site or location?	YES	NO	v	Was the examination carried out: Within an interval of 6 months?	YES	v	NO	
					With an interval of 12 months?	YES		NO
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO		By an examination scheme?	YES	v	NO	
				After the occurrence of exceptional circumstances?	YES		NO	v

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) **NONE**

Is the above a defect which is of immediate danger to persons: YES NO v

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal, or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: (If none state NONE)
Visual And Dimension Check was Carried Out.

IS THIS EQUIPMENT SAFE TO OPERATE? YES v NO

LEEA & ASNT Level II Inspector Name:		Authenticating This Report:	Signature:
Mahmoud Ali Khaled Mahmoud		Ashraf El Said	

THIS IS TO CERTIFY THAT: a competent person did attend the owner mentioner's work location on the date shown above and the Equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

