



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	EMC Company	Certificate no:	QC-B-03-25-0077/02/01
Location:	8 TH STATION	Job Order No.:	QC-B-03-25-0077
Date of Examination:	08-Mar-2025	Next Inspection Due:	07-Sep-2025
Last Inspection		Last Proof Load Test Date	
10-Nov-2024		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
190002738 190002700 190002792	Fall Arrester Manufacturer: KARAM Manufacturer Date: 03/2019 Batch No:S20-006 Wire Rope Length: 20 m Wire Rope Dia: 5 mm	03	140 Kg
Reference Standard:	BS EN 360:2002 / BS EN 363:2018		

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	✓	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?	YES	✓	NO			
						YES		NO	✓		
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO			YES	✓	NO			
						YES		NO	✓		
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE											
Is the above a defect which is of immediate danger to persons:								YES		NO	✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)						N/A					
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:											
Particulars of any tests carried out as part of the examination: (If none state NONE) <i>The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory</i>											
IS THIS EQUIPMENT SAFE TO OPERATE?								YES	✓	NO	

LEEA & ASNT Level II Inspector Name:	Signature	Authenticating This Report:	Signature
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner mentioner's work location on the date shown above and the Equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.







Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	EMC Company	Certificate no:	QC-B-03-25-0077/02/02
Location:	8 TH STATION	Job Order No.:	QC-B-03-25-0077
Date of Examination:	08-Mar-2025	Next Inspection Due:	07-Sep-2025
Last Inspection		Last Proof Load Test Date	
10-Nov-2024		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
190000042 190000054 190000045 190000037	Fall Arrester Manufacturer: KARAM Manufacturer Date: 12/2020 Batch No:00730427 Wire Rope Length: 20 m Wire Rope Dia: 5 mm	04	140 Kg
Reference Standard:	BS EN 360:2002 / BS EN 363:2018		

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	✓	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?	YES	✓	NO			
						YES		NO	✓		
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO			YES	✓	NO			
						YES		NO	✓		
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE											
Is the above a defect which is of immediate danger to persons:								YES		NO	✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)						N/A					
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:											
Particulars of any tests carried out as part of the examination: (If none state NONE) <i>The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory</i>											
IS THIS EQUIPMENT SAFE TO OPERATE?								YES	✓	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner mentioner's work location on the date shown above and the Equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.





Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	EMC Company	Certificate no:	QC-B-03-25-0077/02/03
Location:	8 TH STATION	Job Order No.:	QC-B-03-25-0077
Date of Examination:	08-Mar-2025	Next Inspection Due:	07-Sep-2025
Last Inspection		Last Proof Load Test Date	
10-Nov-2024		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
170749 2565 2339 0474	Fall Arrester Manufacturer: KARAM Manufacturer Date: 03/2019 Batch No:S20-006 Wire Rope Length: 20 m Wire Rope Dia: 5 mm	03	140 Kg
Reference Standard:	BS EN 360:2002 / BS EN 363:2018		

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	v	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?	YES	v	NO			
						YES		NO	v		
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO			YES	v	NO			
						YES		NO	v		
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE											
Is the above a defect which is of immediate danger to persons:								YES		NO	v
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)						N/A					
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:											
Particulars of any tests carried out as part of the examination: (If none state NONE) <i>The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory</i>											
IS THIS EQUIPMENT SAFE TO OPERATE?								YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature	Authenticating This Report:	Signature
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner mentioner's work location on the date shown above and the Equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.





Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	EMC Company	Certificate no:	QC-B-03-25-0077/02/04
Location:	8 TH STATION	Job Order No.:	QC-B-03-25-0077
Date of Examination:	08-Mar-2025	Next Inspection Due:	07-Sep-2025
Last Inspection		Last Proof Load Test Date	
10-Nov-2024		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
180018272 0258	Fall Arrester Manufacturer: KARAM Manufacturer Date: 01/2020 Batch No: 00836074 Wire Rope Length: 15 m Wire Rope Dia: 6 mm	02	150 Kg
Reference Standard:	BS EN 360:2002 / BS EN 363:2018		

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	✓	Was the examination carried out: Within an interval of 6 months?	YES	✓	NO	
						With an interval of 12 months?	YES		NO
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		By an examination scheme?	YES	✓	NO	
					After the occurrence of exceptional circumstances?	YES		NO	✓
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE									
Is the above a defect which is of immediate danger to persons:					YES		NO	✓	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)					N/A				
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none state NONE)									
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory									
IS THIS EQUIPMENT SAFE TO OPERATE?					YES	✓	NO		

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner mentioner's work location on the date shown above and the Equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	EMC Company	Certificate no:	QC-B-03-25-0077/02/05
Location:	8 TH STATION	Job Order No.:	QC-B-03-25-0077
Date of Examination:	08-Mar-2025	Next Inspection Due:	07-Sep-2025
Last Inspection		Last Proof Load Test Date	
10-Nov-2024		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
WM001 WM002	<p>Fall Arrester</p> <p>Manufacturer: WORKMAN</p> <p>Year Of Manufacture: 2021</p> <p>Model: WK PM RFA20</p> <p>Length Of Wire : 20 M</p> <p>Dia Of Wire: 6 MM</p>	02	140 Kg

Reference Standard:	BS EN 360:2002 / BS EN 363:2018
---------------------	---------------------------------

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?	YES	√	NO	
						YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO			YES	√	NO	
						YES		NO	√

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) **NONE**

Is the above a defect which is of immediate danger to persons: YES NO √



Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal, or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: (If none state NONE)

The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory

IS THIS EQUIPMENT SAFE TO OPERATE? YES √ NO

LEEA & ASNT Level II Inspector Name:	Signature	Authenticating This Report:	Signature
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner mentioner's work location on the date shown above and the Equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.