





Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	EMC Company	Certificate no:	QC-B-03-25-0077/09/01
Location:	8 TH STATION	Job Order No.:	QC-B-03-25-0077
Date of Examination:	08-Mar-2025	Next Inspection Due:	07-Sep-2025
Last Inspection		Last Proof Load Test Date	
01-Dec-2024		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
HP01 HP02	Hydraulic Hand Pallet Lift Manufacturer: Hyundai Model: HLP001 Size: (W: 55CM x L: 1.05 M) Fork (13 CM Min Height)	02	3000 kg
Reference Standard:	BS EN 1494		

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?	YES	√	NO	
						YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO			YES	√	NO	
						YES		NO	√
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE									
Is the above a defect which is of immediate danger to persons:						YES		NO	√
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none state NONE) <i>The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory</i>									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	√	NO	

LEEA & ASNT Level II Inspector Name:	Signature	Authenticating This Report:	Signature
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner mentioner's work location on the date shown above and the Equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.