





LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Black Gold Gulf Oil And Gas Services Co.Ltd Basra Iraq	Certificate no:	QC-B-04-25-0198-02
Location:	QC YARD	Job Order No:	QC-B-04-25-0198
Date of Examination:	30-Apr-2025	Next Inspection Due:	29-Oct-2025
Last Inspection		Last Proof Load Test Date	
NEW		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
LS221	<p align="center">Fiberglass Extension Ladder</p> <p>Model : NJS2-116 Manufacture: Yiwu Qingzhu Ladder Co. LTD Manufacture Date : October – 2015 The Inner Width : 390 mm , The out Side Width: 410 mm Extension : b1 = 390 mm , b2 = 410 mm</p>	01	150 Kg
Applicable Reference Standard:	EN 131-3:2007 + A1 : 2011		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√
	Was the examination carried out?		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	
	* Within an interval of 6 months?		YES
* Within an interval of 12 months?		YES	√
* By an examination scheme?		YES	√
* After the occurrence of exceptional circumstances?		YES	√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mahmoud Ali		Mohammed Abdullah	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting




LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

RESULTS INSPECTION ON THE LADDER ACCEPTANCE AS FOLLOWS:

S = SERVICE ABLE
SN = NOT SERVICE ABLE
N.A = NOT APPLICABLE

General	S	SN	N.A.
Ladder free from oil, grease or any slippery.	√		
Ladder free from corrosion / decay.	√		
Ladder free from any sharp Edge/ protrusions.	√		
Ladder rungs / steps in place and secure.	√		
Ladder rungs / steps free from any cracks/decay/corrosion.	√		
Ladder braces / brackets secured	√		
Ladder end cap & foot anti-slip present, secure and good working condition.	√		
Stability of Ladder when positioned flat on the ground.	√		
Extension lock (s)	√		
<p>Note: The inspection must include looking for dents, bends, or excessively dented rungs; and checking all rungs to siderail .connections, checking hardware connections, and checking rivets for shears</p>			

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mahmoud Ali		Mohammed Abdullah	