





### LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client:</b>	Black Gold Gulf Oil And Gas Services Co.Ltd Basra Iraq	<b>Certificate no:</b>	QC-B-04-25-0198-03
<b>Location:</b>	QC YARD	<b>Job Order No:</b>	QC-B-04-25-0198
<b>Date of Examination:</b>	30-Apr-2025	<b>Next Inspection Due:</b>	29-Oct-2025
<b>Last Inspection</b>		<b>Last Proof Load Test Date</b>	
NEW		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
LS222	<p align="center"><b>Fiberglass Extension Ladder</b></p> <p>Model : NJS2-116                      Manufacture: Yiwu Qingzhu Ladder Co. LTD                      Manufacture Date : October – 2015                      The Inner Width : 390 mm , The out Side Width: 410 mm                      Extension : b1 = 390 mm , b2 = 410 mm</p>	01	150 Kg
<b>Applicable Reference Standard:</b>	EN 131-3:2007 + A1 : 2011		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√
	Was the examination carried out?		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	
	* Within an interval of 6 months?		YES √ NO
* Within an interval of 12 months?		YES	NO √
* By an examination scheme?		YES	NO √
* After the occurrence of exceptional circumstances?		YES	NO √
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: <b>None</b>			
Is The Above A Defect Which Is Of Immediate Danger To Persons			YES NO √
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)			NO √ YES By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: <b>None</b>			
<b>** Visual And Dimension Check was Carried Out.</b>			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject √

<b>LEEA &amp; ASNT Level II Inspector Name:</b>	<b>SIGNATURE:</b>	<b>Authenticating This Report:</b>	<b>SIGNATURE:</b>
Mahmoud Ali		Mohammed Abdullah	

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting





## LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION


This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

**RESULTS INSPECTION ON THE LADDER ACCEPTANCE AS FOLLOWS:**

S = SERVICE ABLE  
 SN = NOT SERVICE ABLE  
 N.A = NOT APPLICABLE

General	S	SN	N.A.
Ladder free from oil, grease or any slippery.	√		
Ladder free from corrosion / decay.	√		
Ladder free from any sharp Edge/ protrusions.	√		
Ladder rungs / steps in place and secure.	√		
Ladder rungs / steps free from any cracks/decay/corrosion.	√		
Ladder braces / brackets secured	√		
Ladder end cap & foot anti-slip present, secure and good working condition.	√		
Stability of Ladder when positioned flat on the ground.	√		
Extension lock (s)	√		

**Note:** The inspection must include looking for dents, bends, or excessively dented rungs; and checking all rungs to siderail .connections, checking hardware connections, and checking rivets for shears

LEEA & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mahmoud Ali		Mohammed Abdullah	