






LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Daqing Drilling Company	Certificate no:	QC-B-04-25-0166-06
Location:	DQ Rig 037	Job Order No:	QC-B-04-25-0166
Date of Examination:	09.04.2025	Next Inspection Due:	08.10.2025
Last Inspection		Last Proof Load Test Date	
N/A		N/A	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
B6497	<p align="center"><u>Cat Head Single Wire Rope Sling</u></p> <p>DIAMETER: 26 MM LENGTH: 10 M IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE HARD EYE X PLAN END SAFETY FACTOR 5:1</p> 	01	8.6 TON
Applicable Reference Standard:	BS EN 13414-1:2003+A2:2008		
* Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?		
	YES	NO	√
	* Within an interval of 6 months?		YES
	* Within an interval of 12 months?		YES
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	√
	* By an examination scheme?		YES
		* After the occurrence of exceptional circumstances?	
		YES	NO
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES	NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)		NO	YES
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohammed Abdullah		Ashraf Elsaid	


THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.





LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Daqing Drilling Company	Certificate no:	QC-B-04-25-0166-07
Location:	DQ Rig 037	Job Order No:	QC-B-04-25-0166
Date of Examination:	09.04.2025	Next Inspection Due:	08.10.2025
Last Inspection		Last Proof Load Test Date	
N/A		N/A	

IDENTIFICATION NO	DESCRIPTION	QTY	MBL
C3615	<p><u>Cat Head Single Wire Rope Sling</u></p> <p>DIAMETER: 26 MM LENGTH: 8 M IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE HARD EYE X PLAN END SAFETY FACTOR 5:1</p> 	01	51.5 MT
Applicable Reference Standard:	BS EN 13414-1:2003+A2:2008		
* Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?		
	YES	NO	√
* If the answer to the above question is YES has the equipment been installed correctly?	* Within an interval of 6 months?		√
	* Within an interval of 12 months?		√
* If the answer to the above question is YES has the equipment been installed correctly?	* By an examination scheme?		√
	* After the occurrence of exceptional circumstances?		√
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: None			
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES	NO
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)		NO	√
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: None			
** Visual And Dimension Check was Carried Out.			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject

LEE & ASNT Level II Inspector Name:	SIGNATURE:	Authenticating This Report:	SIGNATURE:
Mohammed Abdullah		Ashraf Elsaid	

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.