





## LIFTING ACCESSORIES OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client:</b>	Al-Karrar Co,	<b>Certificate no:</b>	QC-B-04-25-0189/01
<b>Location:</b>	QC YARD	<b>Job Order No:</b>	QC-B-04-25-0189
<b>Date of Examination:</b>	17-04-2025	<b>Next Inspection Due:</b>	16-10-2025
<b>Last Inspection</b>		<b>Last Proof Load Test Date</b>	
N/A		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
67236-37/2  67236-37/7	<p><b><u>Flat Polyester Webbing Sling.</u></b></p> <p><u>Length : 5 m</u> <u>Color : Blue</u> <u>Manufacturer Date: 10-10-2017</u> <u>Safety Factor : 7:1</u></p> 	02	<p><b>8000 KG Vertical</b></p> <p><b>6400 KG Choker</b></p> <p><b>16000 KG Basket</b></p>
<b>Applicable Reference Standard:</b>	BS EN 1492-1:2000+A1:2008		
* Is this the first examination after installation or assembly at a new site or location?	YES	NO	√
	Was the examination carried out?		
* If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	√
	* Within an interval of 6 months?		YES √ NO
		* Within an interval of 12 months?	
		* By an examination scheme?	
		* After the occurrence of exceptional circumstances?	
Identification Of Any Part Found To Have A Defect Which Is Or Could Become A Danger To Persons And A Description Of The Defect: <b>None</b>			
Is The Above A Defect Which Is Of Immediate Danger To Persons		YES	NO √
Is The Above A Defect Which Is Not Yet But Could Become A Danger To Persons: (If YES State The Date By When)		NO √	YES By:
Particulars Of Any Repair, Renewal, Or Alteration Required To Remedy The Defect Identified Above: <b>None</b>			
<b>** Visual And Dimension Check was Carried Out.</b>			
Is This Equipment Safe To Operate?		Yes Accept	NO Reject

<b>LEE &amp; ASNT Level II Inspector Name:</b>	<b>SIGNATURE:</b>	<b>Authenticating This Report:</b>	<b>SIGNATURE:</b>
Mahmoud Ali		Mohammed Abdulla	

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.