




Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Nujum Al Ebtakr Co,	Certificate no:	QC-B-04-25-0245-02
Location:	Quality Control Yard	Job Order No:	QC-B-04-25-0245
Date of Examination:	05-May-2025	Next Inspection Due:	04-Nov-2025
Last Inspection		Last Proof Load Test Date	
N/A		By Manufacture	

IDENTIFICATION NO	DESCRIPTION	QTY	SWL
M5721A M5721B	Safety pin bow Shackles Size: 7/8" Grade: 6 Manufacturer: GT Safety Factor 6:1	02	6.5 ton



Reference Standard:	BS EN 13889
---------------------	-------------

Is this the first examination after Installation or assembly at a new site or location?	YES	NO	v	Was the examination carried out: Within an interval of 6 months?	YES	v	NO	
					Within an interval of 12 months?	YES		NO
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO		By an examination scheme?	YES	v	NO	
				After the occurrence of exceptional circumstances?	YES		NO	v

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) **NONE**

Is the above a defect which is of immediate danger to persons: YES NO v


Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal, or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: (If none state NONE)

The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Ashraf ElSaid	

THIS IS TO CERTIFY THAT: a competent person did attend the owner mentioner's work location on the date shown above and the Equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

