




## Visual & Magnetic Particles Examination Report

Client:	Taqw Alrumaila co	Certificate no:	QC-B-06-25-0372/01
Location:	Weatherford - Base	Job Order No:	QC-B-06-25-0372
Date of Examination:	22.June.2025	Next Inspection Due:	21.Dec.2025
Unit Serial Number	Description of the examined equipment	Result	
011532-2013	Hydraulic Spooling Air Motor Base Welding Area	Accept	



### NDT Equipment Details

Standard	ASTM E 709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-10	Due Date	10.Nov.2025
White Contrast	WCP-2	Batch No:	008A009	Due Date	April.2026
Black Ink	7HF	Batch No:	008A103	Due Date	Jun.2026

### NDT procedure

Visual and MPI were carried out for the above description and found free of surface defects at the time of inspection

Identification of any part found to have a defect and a description of the defect: None

Particulars of any repair, renewal, or alteration required to remedy the defect identified above: None

All MPI was performed per OEM's instructions, and OEM did the measurements.

LEEA & ASNT Level II Inspector Name:	Signature	Authenticating This Report:	Signature
Jaafar Bader		Mohammed Abdulla	