

**AI TAKAMUL COMPANY FOR ENGINEERING TESTS  
AND PROFESSIONAL SAFETY LIMITED**

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: [OP@qualitycontrol-iraq.com](mailto:OP@qualitycontrol-iraq.com) / [hany.akafi@qualitycontrol-iraq.com](mailto:hany.akafi@qualitycontrol-iraq.com)




**CERTIFICATE OF THOROUGH EXAMINATION**

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Date of Examination:</b>	13/08/2025	<b>Date of Report:</b>	13/08/2025	<b>Certificate No:</b>	QC-25/-WPS-1308-075		
<b>Client Name:</b>	HALLIBURTON	<b>Location:</b>	WPS	<b>Job Number:</b>	13082025		
<b>Serial Number:</b>	QTY	<b>Description</b>	<b>SWL</b>	<b>Date of manufacture if known:</b>	<b>Date of last thorough examination</b>		
H4419	01	<p align="center"><b><u>SAFETY PIN BOW SHACKLE</u></b></p> <p><b>MANUFACTURER: KF</b></p> <p><b>SIZE: 7/8"</b></p> <p><b>GRADE: 6</b></p> <p><b>FOS: 5:1</b></p>	6.5 TON	N/A	22/02/2025		
<b>Reference Standard:</b>	BS EN 13889/ HAL DOC: ST-GL-HAL-HSE-0420						
Is this the first examination after Installation or assembly at a new site or location?		YES	NO	✓	Was the examination carried out: Within an interval of 6 months?		
If the answer to the above question is YES has the equipment been installed correctly?		YES	NO		Was the examination carried out: Within an interval of 12 months?		
					In accordance with an examination scheme?		
					After the occurrence of exceptional circumstances?		
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE							
Is the above a defect which is of immediate danger to persons:					YES	NO	✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)					N/A		
Particulars of any repair, renewal or alteration required to remedy the defect identified above:							
Particulars of any tests carried out as part of the examination: (If none state NONE)							
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory							
<b>IS THIS EQUIPMENT SAFE TO OPERATE?</b>					YES	NO	✓
<b>Name of Inspector:</b>	<b>Name of person authenticating this report:</b>		<b>Client Signature &amp; Stamp:</b>				
ASHRAF ELSAID	MOHAMED ABDALLAH		<p><b>ALI Talib HB48903</b></p> <p>Date: 13-08-2025</p> <p>Signature </p> <p>Halliburton</p>				
<b>Date of Next Through Examination:</b>	12/02/2026						

REV: 01 Dated: 20 June 2022



**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of inspection and considered Safe for Lifting.

