

**AI TAKAMUL COMPANY FOR ENGINEERING TESTS
AND PROFESSIONAL SAFETY LIMITED**

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com




CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	13/08/2025	Date of Report:	13/08/2025	Certificate No:	QC-25/-WPS-1308-089
Client Name:	HALLIBURTON	Location:	WPS	Job Number:	13082025
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
55213258	1	<u>FLAT POLYESTER WOVEN WEBBING SLING</u> Manufacture: Delta plus Material: Polyester Safety Factor: 7:1 Length: 1 M Color: Violet	Vertical 1000 kg Chocker 800 Kg Basket 2000 kg	11/2024	22/02/2025
Reference Standard:		BS EN 1492-1/ HAL DOC: ST-GL-HAL-HSE-0420			
Is this the first examination after Installation or assembly at a new site or location?		☐ YES ☒ NO ☐ ✓		Was the examination carried out: Within an interval of 6 months? ☐ YES ☒ NO ☐ ✓ With an interval of 12 months? ☐ YES ☐ NO ☒ ✓ In accordance with an examination scheme? ☐ YES ☒ NO ☐ ✓ After the occurrence of exceptional circumstances? ☐ YES ☐ NO ☒ ✓	
If the answer to the above question is YES has the equipment been installed correctly?		☐ YES ☐ NO ☐ ✓			
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				☐ YES ☐ NO ☒ ✓	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				N/A	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				☐ YES ☒ ✓ ☐ NO ☐ ✓	
Name of Inspector:	Name of person authenticating this report:		Client Signature & Stamp:		
ASHRAF ELSAID	MOHAMED ABDALLAH		ALI Talib HB48903 Date: 13-08-2025 Signature Haliburton		
Date of Next Through Examination:	12/02/2026				

REV: 01 Dated: 20 June 2022



THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

