



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations


Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-06-01
Location:	Degassing Station 5	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2026
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
T18040414	01	Chain Hoist Manufacture: TOYO Model: TCB-020 Lift: 3m Grade: 80 F.O.S: 4:1 Location: Station	2 Ton



Reference Standard: BS EN 13157: 2004 + A1: 2009

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within an interval of 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	v		YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	v	NO	
						YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-06-02
Location:	Degassing Station 5	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2026
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
2511019 2511016	02	Lever Block Manufacture: TOYO Lift: 1.5m Grade: 80 F.O.S: 4:1 Location: Station	1.5 Ton

Reference Standard: BS EN 13157: 2004 + A1: 2009

Is this the first examination after Installation or assembly at a new site or location?	YES	NO	v	Was the examination carried out? Within an interval of 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?	YES	v	NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES	NO	v	Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE	YES	v	NO	v
Is the above a defect that is of immediate danger to persons?					YES	v	NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)					N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:								
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.								
IS THIS EQUIPMENT SAFE TO OPERATE?					YES	v	NO	v

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-06-03
Location:	Degassing Station 5	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2026
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
VC01 VC02 VC03 VC04	04	Lever Block Manufacture: TOYO VC Lift: 1.5m Grade: 80 F.O.S: 4:1 Location: Station	1.5 Ton

Reference Standard: BS EN 13157: 2004 + A1: 2009

Is this the first examination after Installation or assembly at a new site or location?	YES	NO	v	Was the examination carried out? Within an interval of 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?	YES	v	NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES	NO	v	Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE	YES	v	NO	v
Is the above a defect that is of immediate danger to persons?					YES	v	NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)					N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:								
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.								
IS THIS EQUIPMENT SAFE TO OPERATE?					YES	v	NO	v

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.