



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-07-01
Location:	Degassing Station 5	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
2024091783 2024091780	02	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: TOYOVC Date of Manufacture: 09/2024 Material: 100% PES, Colour: YELLOW Length: 6 m Safety Factor: 7:1 Location: Station 	3000 KG Vertical 2400 KG Choker 6000 KG Basket

Reference Standard: BS EN 1492-1:2000-A1:2008

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within an interval of 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	√		YES	√	NO	
						YES		NO	√
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	√	NO	
						YES		NO	√
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	√
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	√	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person has attended the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination


This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-07-02
Location:	Degassing Station 5	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
24082513234 24082513245	02	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: SUPERTEX Date of Manufacture: 08/2024 Material: 100% PES, Colour: BROWN Length: 6 m Safety Factor: 7:1  Location: Station	6000 KG Vertical 4800 KG Choker 12000 KG Basket

Reference Standard: BS EN 1492-1:2000-A1:2008

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within an interval of 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	✓		YES	✓	NO	
						YES		NO	✓
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	✓	NO	
						YES		NO	✓
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	✓
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	✓	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person has attended the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination


This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-07-03
Location:	Degassing Station 5	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
2024010257	01	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: TOYOVC Date of Manufacture: 01/2024 Material: 100% PES, Colour: BROWN Length: 6 m Safety Factor: 7:1  Location: Station	6000 KG Vertical 4800 KG Choker 12000 KG Basket

Reference Standard: BS EN 1492-1:2000-A1:2008

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within an interval of 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	√		YES	√	NO	
						YES		NO	√
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	√	NO	
						YES		NO	√
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	√
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	√	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person has attended the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-07-04
Location:	Degassing Station 5	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
2024092038 2024092023 2024092011 2024092158	04	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: TOYOVC Date of Manufacture: 09/2024 Material: 100% PES, Colour: GREY Length: 6 m Safety Factor: 7:1 Location: Station	4000 KG Vertical 3200 KG Choker 8000 KG Basket



Reference Standard:	BS EN 1492-1:2000-A1:2008
---------------------	---------------------------

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	v	Was the examination carried out? Within an interval of 6 months?	YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO		By an examination scheme?	YES	v	NO	
					After the occurrence of exceptional circumstances?	YES		NO	v

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE)
NONE

Is the above a defect that is of immediate danger to persons? YES NO v



Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which) N/A

Particulars of any repair, renewal, or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: (If none, state NONE)

The subject Items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.

IS THIS EQUIPMENT SAFE TO OPERATE? YES v NO

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person has attended the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination



This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-07-05
Location:	Degassing Station 5	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
7620220544	01	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: GS Date of Manufacture: 2022 Material: 100% PES, Colour: GREY Length: 4 m Safety Factor: 7:1 Location: Station 	4000 KG Vertical 3200 KG Choker 8000 KG Basket

Reference Standard: BS EN 1492-1:2000-A1:2008

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within an interval of 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	✓		YES	✓	NO	
						YES		NO	✓
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	✓	NO	
						YES		NO	✓
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	✓
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	✓	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person has attended the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-07-06
Location:	Degassing Station 5	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
5110204084 5110204114	02	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: GS Date of Manufacture: 05/2023 Material: 100% PES, Colour: GREEN Length: 4 m Safety Factor: 7:1 Location: Station	2000 KG Vertical 1600 KG Choker 4000 KG Basket



Reference Standard:	BS EN 1492-1:2000-A1:2008
---------------------	---------------------------

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within an interval of 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	√		YES	√	NO	
						YES		NO	√
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	√	NO	
						YES		NO	√
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	√
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	√	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person has attended the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination


This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-07-07
Location:	Degassing Station 5	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
12260852 12260713	02	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: TOHO Date of Manufacture: 11/2022 Material: 100% PES, Colour: GREEN Length: 4 m Safety Factor: 7:1  Location: Station	2000 KG Vertical 1600 KG Choker 4000 KG Basket

Reference Standard: BS EN 1492-1:2000-A1:2008

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	v	Was the examination carried out? Within an interval of 6 months?	YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO		With an interval of 12 months?	YES	v	NO	
					By an examination scheme?	YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE)					After the occurrence of exceptional circumstances?	YES		NO	v
NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)					N/A				
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE)									
The subject Items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?							YES	v	NO

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person has attended the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination


This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-07-08
Location:	Degassing Station 5	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
2047	01	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: DELTAPLUS Date of Manufacture: 02/2024 Material: 100% PES, Colour: BROWN Length: 6 m Safety Factor: 7:1  Location: Station	6000 KG Vertical 4800 KG Choker 12000 KG Basket

Reference Standard: BS EN 1492-1:2000-A1:2008

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within an interval of 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	√		YES	√	NO	
						YES		NO	√
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	√	NO	
						YES		NO	√
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	√
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	√	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person has attended the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations


Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-07-09
Location:	Degassing Station 5	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
5110102004 5110102039	02	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: GS Date of Manufacture: 05/2023 Material: 100% PES, Colour: PURPLE Length: 2 m Safety Factor: 7:1 Location: Station	1000 KG Vertical 800 KG Choker 2000 KG Basket



Reference Standard: BS EN 1492-1:2000-A1:2008

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	✓	Was the examination carried out? Within an interval of 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?	YES	✓	NO		
						YES		NO	✓	
	YES		NO			YES	✓	NO		
If the answer to the above question is YES, has the equipment been installed correctly?						YES		NO	✓	
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE										
Is the above a defect that is of immediate danger to persons?							YES		NO	✓
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A				
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:										
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.										
IS THIS EQUIPMENT SAFE TO OPERATE?							YES	✓	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person has attended the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.