



Lifting Accessories of Visual and Thorough Examination


This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-08-01
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
D213-1219	01	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: WEBBLON Date of Manufacture: 08/2021 Material: 100% PES, Colour: YELLOW Length: 3 m Safety Factor: 7:1 Location: WORKSHOP 	3000 KG Vertical 2400 KG Choker 6000 KG Basket

Reference Standard: BS EN 1492-1:2000-A1:2008

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within an interval of 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	v		YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	v	NO	
						YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination


This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-08-02
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
2024091662 2024091815	02	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: TOYOVC Date of Manufacture: 09/2024 Material: 100% PES, Colour: YELLOW Length: 6 m Safety Factor: 7:1 Location: WORKSHOP 	3000 KG Vertical 2400 KG Choker 6000 KG Basket

Reference Standard: BS EN 1492-1:2000-A1:2008

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within an interval of 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	v		YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	v	NO	
						YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-08-03
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
92092-14/39 92092-14/9 92092-14/42 92092-14/4	04	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: LIFTEK Date of Manufacture: 01/2022 Material: 100% PES, Colour: YELLOW Length: 3 m Safety Factor: 7:1 Location: WORKSHOP	3000 KG Vertical 2400 KG Choker 6000 KG Basket



Reference Standard:	BS EN 1492-1:2000-A1:2008
---------------------	---------------------------

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	v	Was the examination carried out? Within an interval of 6 months?	YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO		By an examination scheme?	YES	v	NO	
					After the occurrence of exceptional circumstances?	YES		NO	v

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE)
NONE

Is the above a defect that is of immediate danger to persons? YES NO v


Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which) N/A

Particulars of any repair, renewal, or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: (If none, state NONE)

The subject Items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.

IS THIS EQUIPMENT SAFE TO OPERATE? YES v NO

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination


This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-08-04
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
12260853 12260808	02	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: TOHO Date of Manufacture: 09/2024 Material: 100% PES, Colour: GREEN Length: 4 m Safety Factor: 7:1 Location: WORKSHOP 	2000 KG Vertical 1600 KG Choker 4000 KG Basket

Reference Standard: BS EN 1492-1:2000-A1:2008

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within an interval of 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	v		YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	v	NO	
						YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations


Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-08-05
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
5110204136 5110204107 5110204110 5110204120	04	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: GS Date of Manufacture: 05/2023 Material: 100% PES, Colour: GREEN Length: 4 m Safety Factor: 7:1 Location: WORKSHOP	2000 KG Vertical 1600 KG Choker 4000 KG Basket



Reference Standard:	BS EN 1492-1:2000-A1:2008
---------------------	---------------------------

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within an interval of 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	v		YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	v	NO	
						YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination


This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-08-06
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
109987-8/67 109987-8/36	02	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: LIFTEK Date of Manufacture: 07/2025 Material: 100% PES, Colour: GREEN Length: 6 m Safety Factor: 7:1 Location: WORKSHOP 	2000 KG Vertical 1600 KG Choker 4000 KG Basket

Reference Standard: BS EN 1492-1:2000-A1:2008

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	v	Was the examination carried out? Within an interval of 6 months?	YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO		By an examination scheme?	YES	v	NO	
					After the occurrence of exceptional circumstances?	YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE)									
NONE									
Is the above a defect that is of immediate danger to persons?								YES	
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)									
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE)									
The subject Items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?								YES	v

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination


This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-08-07
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
2024092014 2024092151	02	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: TOYOVC Date of Manufacture: 09/2024 Material: 100% PES, Colour: GREY Length: 6 m Safety Factor: 7:1 Location: WORKSHOP 	4000 KG Vertical 3200 KG Choker 8000 KG Basket

Reference Standard: BS EN 1492-1:2000-A1:2008

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within an interval of 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	v		YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	v	NO	
						YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination


This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-08-08
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
113367-16/5 113367-16/50	02	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: TOYOVC Date of Manufacture: 01/2026 Material: 100% PES, Colour: GREY Length: 6 m Safety Factor: 7:1 Location: WORKSHOP 	4000 KG Vertical 3200 KG Choker 8000 KG Basket

Reference Standard: BS EN 1492-1:2000-A1:2008

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	v	Was the examination carried out? Within an interval of 6 months?	YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO		With an interval of 12 months?	YES	v	NO	
					By an examination scheme?	YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE)					After the occurrence of exceptional circumstances?	YES		NO	v
NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)					N/A				
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE)									
The subject Items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?							YES	v	NO

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination


This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-08-09
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
2530230272 2530230223 2530230369 2530230511	04	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: SUPERTEX Date of Manufacture: 09/2025 Material: 100% PES, Colour: GREY Length: 4 m Safety Factor: 7:1 Location: WORKSHOP 	4000 KG Vertical 3200 KG Choker 8000 KG Basket

Reference Standard: BS EN 1492-1:2000-A1:2008

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	v	Was the examination carried out? Within an interval of 6 months?	YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO		With an interval of 12 months?	YES	v	NO	
					By an examination scheme?	YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE)					After the occurrence of exceptional circumstances?	YES		NO	v
NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)					N/A				
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE)									
The subject Items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?							YES	v	NO

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination


This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-08-10
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
1261-4T/6M-12	01	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: DAWSON Date of Manufacture: 11/2022 Material: 100% PES, Colour: GREY Length: 6 m Safety Factor: 7:1 Location: WORKSHOP 	4000 KG Vertical 3200 KG Choker 8000 KG Basket

Reference Standard: BS EN 1492-1:2000-A1:2008

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	v	Was the examination carried out? Within an interval of 6 months?	YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO		With an interval of 12 months?	YES	v	NO	
					By an examination scheme?	YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE)					After the occurrence of exceptional circumstances?	YES		NO	v
NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)					N/A				
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE)									
The subject Items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?							YES	v	NO

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination


This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-08-11
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
03499	01	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: GS Date of Manufacture: 2022 Material: 100% PES, Colour: GREY Length: 6 m Safety Factor: 7:1 Location: WORKSHOP 	4000 KG Vertical 3200 KG Choker 8000 KG Basket

Reference Standard: BS EN 1492-1:2000-A1:2008

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	v	Was the examination carried out? Within an interval of 6 months?	YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO		With an interval of 12 months?	YES	v	NO	
					By an examination scheme?	YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE)					After the occurrence of exceptional circumstances?	YES		NO	v
NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)					N/A				
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE)									
The subject Items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?							YES	v	NO

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-08-12
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
88297-25/1 88297-25/34 88297-25/28 88297-25/27	04	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: LIFTEK Date of Manufacture: 02/2021 Material: 100% PES, Colour: RED Length: 2 m Safety Factor: 7:1 Location: WORKSHOP	5000 KG Vertical 4000 KG Choker 10000 KG Basket



Reference Standard:	BS EN 1492-1:2000-A1:2008
---------------------	---------------------------

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	v	Was the examination carried out? Within an interval of 6 months?	YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO		By an examination scheme?	YES	v	NO	
					After the occurrence of exceptional circumstances?	YES		NO	v

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE)
NONE

Is the above a defect that is of immediate danger to persons? YES ☐ NO ☒


Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which) N/A

Particulars of any repair, renewal, or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: (If none, state NONE)

The subject Items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.

IS THIS EQUIPMENT SAFE TO OPERATE? YES ☒ NO ☐

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-08-13
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
113367-20/52 11367-20/72	02	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: LIFTEK Date of Manufacture: 01/2026 Material: 100% PES, Colour: BROWN Length: 6 m Safety Factor: 7:1 Location: WORKSHOP 	6000 KG Vertical 4800 KG Choker 12000 KG Basket

Reference Standard: BS EN 1492-1:2000-A1:2008

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	v	Was the examination carried out? Within an interval of 6 months?	YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO		By an examination scheme?	YES	v	NO	
					After the occurrence of exceptional circumstances?	YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE)									
NONE									
Is the above a defect that is of immediate danger to persons?								YES	
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)									
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE)									
The subject Items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?								YES	v

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination


This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-08-14
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
24082513295 2527582389	02	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: SUPERTEX Date of Manufacture: 02/2025 Material: 100% PES, Colour: BROWN Length: 6 m Safety Factor: 7:1 Location: WORKSHOP 	6000 KG Vertical 4800 KG Choker 12000 KG Basket

Reference Standard: BS EN 1492-1:2000-A1:2008

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within an interval of 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	v		YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	v	NO	
						YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-08-15
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
6406 6418	02	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: DELTAPLUS Material: 100% PES, Colour: ORANGE Length: 10 m Safety Factor: 7:1 Location: WORKSHOP	10000 KG Vertical 8000 KG Choker 20000 KG Basket



Reference Standard:	BS EN 1492-1:2000-A1:2008												
Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within an interval of 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?								
	YES		NO	√		YES	√	NO					
						YES		NO	√				
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	√	NO					
						YES		NO	√				
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE													
Is the above a defect that is of immediate danger to persons?										YES		NO	√
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)							N/A						
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:													
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.													
IS THIS EQUIPMENT SAFE TO OPERATE?										YES	√	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person has attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination


This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-08-16
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
5110808026	01	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: GS Date of Manufacture: 05/2023 Material: 100% PES, Colour: BLUE Length: 8 m Safety Factor: 7:1 Location: WORKSHOP 	8000 KG Vertical 6400 KG Choker 16000 KG Basket

Reference Standard: BS EN 1492-1:2000-A1:2008

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within an interval of 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	v		YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	v	NO	
						YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination


This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-08-17
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
3601-1T/2M-205 3601-1T/2M-308 3601-1T/2M-259	03	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: DAWSON Date of Manufacture: 01/2025 Material: 100% PES, Colour: PURPLE Length: 2 m Safety Factor: 7:1 Location: WORKSHOP 	1000 KG Vertical 800 KG Choker 2000 KG Basket

Reference Standard: BS EN 1492-1:2000-A1:2008

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within an interval of 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	v		YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	v	NO	
						YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations


Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-08-18
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
5110102008 5110102064 5110102054 5110102070 5110102030	05	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: GS Date of Manufacture: 05/2023 Material: 100% PES, Colour: PURPLE Length: 2 m Safety Factor: 7:1 Location: WORKSHOP	1000 KG Vertical 800 KG Choker 2000 KG Basket



Reference Standard:	BS EN 1492-1:2000-A1:2008
---------------------	---------------------------

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	v	Was the examination carried out? Within an interval of 6 months?	YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO		By an examination scheme?	YES	v	NO	
					After the occurrence of exceptional circumstances?	YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE)									
NONE									
Is the above a defect that is of immediate danger to persons?								YES	
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)									
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE)									
The subject Items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?								YES	v

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination


This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-08-19
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
91581-7/17 91680-4/5	02	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: LIFTEK Date of Manufacture: 12/2021 Material: 100% PES, Colour: PURPLE Length: 2 m Safety Factor: 7:1 Location: WORKSHOP 	1000 KG Vertical 800 KG Choker 2000 KG Basket

Reference Standard: BS EN 1492-1:2000-A1:2008

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	v	Was the examination carried out? Within an interval of 6 months?	YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO		With an interval of 12 months?	YES	v	NO	
					By an examination scheme?	YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE)					After the occurrence of exceptional circumstances?	YES		NO	v
NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)					N/A				
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE)									
The subject Items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?							YES	v	NO

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination


This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-08-20
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-Mar-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
96962-31/91 91581-8/19 96962-31/65	02	Flat Woven Webbing Sling Double Ply Folded Eye at both ends Manufacturer: LIFTEK Date of Manufacture: 12/2021 Material: 100% PES, Colour: PURPLE Length: 3 m Safety Factor: 7:1 Location: WORKSHOP 	1000 KG Vertical 800 KG Choker 2000 KG Basket

Reference Standard: BS EN 1492-1:2000-A1:2008

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	v	Was the examination carried out? Within an interval of 6 months?	YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO		With an interval of 12 months?	YES	v	NO	
					By an examination scheme?	YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE)					After the occurrence of exceptional circumstances?	YES		NO	v
NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)					N/A				
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE)									
The subject Items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?							YES	v	NO

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Khaled Mahmoud		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.