



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-09-01
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-MARCH-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
2107056 2107057 2107058 2107059	04	Vertical Plate Lifting Clamp Manufacturer: GRIPTION Jaw Opening: 0-50 mm Safety Factor: 4:1 Location: Workshop	5 ton



Reference Standard:	BS EN 13155: 2003+A2:2009 / EN 12195
---------------------	--------------------------------------

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	v	Was the examination carried out? Within an interval of 6 months?	YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO		By an examination scheme? After the occurrence of exceptional circumstances?	YES	v	NO	
						YES		NO	v

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE)
NONE

Is the above a defect that is of immediate danger to persons? YES YES NO v

Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which) N/A

Particulars of any repair, renewal, or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: (If none, state NONE)

The subject Items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.

IS THIS EQUIPMENT SAFE TO OPERATE? YES v NO

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Karrar Ali		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-09-02
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-MARCH-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
2103202 2103208	02	Vertical Plate Lifting Clamp Manufacturer: GRIPTION Jaw Opening: 0-40 mm Safety Factor: 4:1 Location: Workshop	2 ton



Reference Standard:	BS EN 13155: 2003+A2:2009 / EN 12195
---------------------	--------------------------------------

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	v	Was the examination carried out? Within an interval of 6 months?	YES	v	NO	
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO		With an interval of 12 months?	YES		NO	v
					By an examination scheme?	YES	v	NO	
					After the occurrence of exceptional circumstances?	YES		NO	v

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE)
NONE

Is the above a defect that is of immediate danger to persons? YES ☐ NO ☐ v ☒

Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which) N/A

Particulars of any repair, renewal, or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: (If none, state NONE)

The subject Items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.

IS THIS EQUIPMENT SAFE TO OPERATE? YES ☐ v ☒ NO ☐

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Karrar Ali		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-09-03
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
NEW		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
20251163 20251185 20251153 20251173 20251183 20251155 20251165 20251175	08	Vertical Plate Lifting Clamp Manufacturer: TOYOVC Jaw Opening: 0-40 mm Safety Factor: 4:1 Location: Workshop	2 ton



Reference Standard:	BS EN 13155: 2003+A2:2009 / EN 12195		
Is this the first examination after Installation or assembly at a new site or location?	YES	NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES	NO	
Was the examination carried out?			
Within an interval of 6 months?		YES	v NO
With an interval of 12 months?		YES	NO v
By an examination scheme?		YES	v NO
After the occurrence of exceptional circumstances?		YES	NO v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE)			
NONE			
Is the above a defect that is of immediate danger to persons?			YES NO v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)			N/A
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:			
Particulars of any tests carried out as part of the examination: (If none, state NONE)			
The subject Items were inspected visually and dimensionally, and no signs of defects were observed at the time of inspection; they were found to be satisfactory.			
IS THIS EQUIPMENT SAFE TO OPERATE?			YES v NO

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Karrar Ali		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for