




Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-10-01
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-MARCH-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
A601	01	Safety Pin Bow Shackles Size: 2 " Grade: 6 Manufacturer: CROSBY Safety Factor 6:1 Location: Workshop 	35 Ton

Reference Standard: BS EN 13889

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	v		YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	v	NO	
						YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, where no signs of defects were observed at the time of inspection, and were found satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Karrar Ali		Mohamed Abdulla	


THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-10-02
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-MARCH-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
04	01	Safety Pin Bow Shackles Size: 2 " Grade: 6 Manufacturer: GP HOLLAND Safety Factor 6:1 Location: Workshop 	35 Ton

Reference Standard: BS EN 13889

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	v		YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	v	NO	
						YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, where no signs of defects were observed at the time of inspection, and were found satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Karrar Ali		Mohamed Abdulla	


THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-10-03
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-MARCH-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
888M	01	Safety Pin Bow Shackles Size: 1 3/4" Grade: 6 Manufacturer: CS Safety Factor 6:1 Location: Workshop 	25 Ton

Reference Standard: BS EN 13889

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	v		YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	v	NO	
						YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, where no signs of defects were observed at the time of inspection, and were found satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Karrar Ali		Mohamed Abdulla	


THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-10-04
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-MARCH-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
TH277	01	Safety Pin Bow Shackles Size: 1 3/4" Grade: 6 Manufacturer: LIFTINGEAR Safety Factor 6:1 Location: Workshop 	25 Ton

Reference Standard: BS EN 13889

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	v		YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	v	NO	
						YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, where no signs of defects were observed at the time of inspection, and were found satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Karrar Ali		Mohamed Abdulla	


THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-10-05
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-MARCH-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
05	01	Safety Pin Bow Shackles Size: 1 3/4" Grade: 6 Manufacturer: GP HOLLAND Safety Factor 6:1 Location: Workshop 	25 Ton

Reference Standard: BS EN 13889

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	v		YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	v	NO	
						YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, where no signs of defects were observed at the time of inspection, and were found satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Karrar Ali		Mohamed Abdulla	


THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-10-06
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-MARCH-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
01	01	Safety Pin Bow Shackles Size: 1 3/4" Grade: 6 Manufacturer: GUNNEBO Safety Factor 6:1 Location: Workshop 	25 Ton

Reference Standard: BS EN 13889

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	v		YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	v	NO	
						YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, where no signs of defects were observed at the time of inspection, and were found satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Karrar Ali		Mohamed Abdulla	


THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-10-07
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-MARCH-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
B8 B9	02	Safety Pin Bow Shackles Size: 1 1/2" Grade: 6 Manufacturer: GT Safety Factor 6:1 Location: Workshop 	17 Ton

Reference Standard: BS EN 13889

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	v		YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	v	NO	
				YES			NO	v	
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, where no signs of defects were observed at the time of inspection, and were found satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Karrar Ali		Mohamed Abdulla	


THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-10-08
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-MARCH-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
B1 H1 M1	03	Safety Pin Bow Shackles Size: 1 1/2" Grade: 6 Manufacturer: TOYOLIFT Safety Factor 6:1 Location: Workshop 	17 Ton

Reference Standard: BS EN 13889

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	v	Was the examination carried out? Within 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
						YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	v	NO	
						YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, where no signs of defects were observed at the time of inspection, and were found satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Karrar Ali		Mohamed Abdulla	


THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-10-09
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-MARCH-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
W4455 W4461 W4490 W4462 W4459	05	Safety Pin Bow Shackles Size: 1 " Grade: 6 Manufacturer: K.F Safety Factor 6:1 Location: Workshop 	8.5 Ton

Reference Standard: BS EN 13889

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	v		YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	v	NO	
						YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, where no signs of defects were observed at the time of inspection, and were found satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Karrar Ali		Mohamed Abdulla	


THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-10-10
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-MARCH-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
D1611 D2605	02	Safety Pin Bow Shackles Size: 1 " Grade: 6 Manufacturer: BASH-P Safety Factor 6:1 Location: Workshop 	8.5 Ton

Reference Standard: BS EN 13889

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	v		YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	v	NO	
						YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, where no signs of defects were observed at the time of inspection, and were found satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Karrar Ali		Mohamed Abdulla	


THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-10-11
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-MARCH-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
B8228	01	Safety Pin Bow Shackles Size: 1 " Grade: 6 Manufacturer: TOYOLIFT Safety Factor 6:1 Location: Workshop 	8.5 Ton

Reference Standard: BS EN 13889

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	v		YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	v	NO	
						YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, where no signs of defects were observed at the time of inspection, and were found satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Karrar Ali		Mohamed Abdulla	


THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-10-12
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-MARCH-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
113A 116A	02	Safety Pin Bow Shackles Size: 7/8 " Grade: 6 Manufacturer: MCKAT Safety Factor 6:1 Location: Workshop 	6.5 Ton

Reference Standard: BS EN 13889

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	v		YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	v	NO	
						YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, where no signs of defects were observed at the time of inspection, and were found satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Karrar Ali		Mohamed Abdulla	


THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-10-13
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-MARCH-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
03 22 24A	03	Safety Pin Bow Shackles Size: 7/8 " Grade: 6 Manufacturer: TOYOLIFT Safety Factor 6:1 Location: Workshop 	6.5 Ton

Reference Standard: BS EN 13889

Is this the first examination after Installation or assembly at a new site or location?				Was the examination carried out? Within 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?					
	YES		NO		v	YES	v	NO	
					YES		NO	v	
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	v	NO	
				YES			NO	v	
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)					N/A				
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, where no signs of defects were observed at the time of inspection, and were found satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Karrar Ali		Mohamed Abdulla	


THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-10-14
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-MARCH-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
A8646	01	Safety Pin Bow Shackles Size: 7/8 " Grade: 6 Manufacturer: GT Safety Factor 6:1 Location: Workshop 	6.5 Ton

Reference Standard: BS EN 13889

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	v		YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	v	NO	
						YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, where no signs of defects were observed at the time of inspection, and were found satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Karrar Ali		Mohamed Abdulla	


THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-10-15
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-MARCH-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
C0690	01	Safety Pin Bow Shackles Size: 7/8 " Grade: 6 Manufacturer: CROSBY Safety Factor 6:1 Location: Workshop 	6.5 Ton

Reference Standard: BS EN 13889

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	v		YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	v	NO	
						YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, where no signs of defects were observed at the time of inspection, and were found satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Karrar Ali		Mohamed Abdulla	


THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-10-16
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-MARCH-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
A1	01	Safety Pin Bow Shackles Size: 7/8 " Grade: 6 Manufacturer: DY15 Safety Factor 6:1 Location: Workshop 	6.5 Ton

Reference Standard: BS EN 13889

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	v		YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	v	NO	
						YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, where no signs of defects were observed at the time of inspection, and were found satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Karrar Ali		Mohamed Abdulla	


THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-10-17
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-MARCH-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
C4	01	Safety Pin Bow Shackles Size: 1 1/8 " Grade: 6 Manufacturer: TOYOLIFT Safety Factor 6:1 Location: Workshop 	9.5 Ton

Reference Standard: BS EN 13889

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	v		YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	v	NO	
						YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, where no signs of defects were observed at the time of inspection, and were found satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Karrar Ali		Mohamed Abdulla	


THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-10-18
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-MARCH-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
A145 A148	02	Safety Pin Bow Shackles Size: 1 1/8 " Grade: 6 Manufacturer: K.F Safety Factor 6:1 Location: Workshop 	9.5 Ton

Reference Standard: BS EN 13889

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	v		YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	v	NO	
						YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, where no signs of defects were observed at the time of inspection, and were found satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Karrar Ali		Mohamed Abdulla	


THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Lifting Accessories of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client:	Egyptian Maintenance Company	Certificate no:	QC-B-09-26-202-10-19
Location:	WORKSHOP	Job Order No:	QC-B-09-26-202
Date of Examination:	14-SEP-2026	Next Inspection Due:	13-MARCH-2027
Date of last Thorough examination		Last Proof Load Test Date	
08-MARCH-2026		By Manufacture	

IDENTIFICATION NO	QTY	DESCRIPTION	SWL
D4639 D2631	02	Safety Pin Bow Shackles Size: 1 1/8 " Grade: 6 Manufacturer: BASH-P Safety Factor 6:1 Location: Workshop 	9.5 Ton

Reference Standard: BS EN 13889

Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out? Within 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?				
	YES		NO	v		YES	v	NO	
						YES		NO	v
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO			YES	v	NO	
						YES		NO	v
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none, state NONE) NONE									
Is the above a defect that is of immediate danger to persons?						YES		NO	v
Is the above a defect that is not yet, but could become a danger to persons (If YES, state the date by which)						N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none, state NONE) The subject Items were inspected visually and dimensionally, where no signs of defects were observed at the time of inspection, and were found satisfactory.									
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	v	NO	

LEEA & ASNT Level II Inspector Name:	Signature:	Authenticating This Report:	Signature:
Karrar Ali		Mohamed Abdulla	

THIS IS TO CERTIFY THAT: a competent person did attend the owner-mentioned work location on the date shown above, and the Equipment described in this report was tested & inspected as per the requirements of the Lifting Operations and Lifting Equipment Regulation (LOLER). The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.