




CERTIFICATION OF VISUAL, THOROUGH EXAMINATION & MAGNETIC PARTICLE INSPECTION			
Client:	HALLIBURTON SPERRY	Report No:	QC-24-01/HAL-SPY-11/C1A
Location:	ZPEC RIG 25	Job Number:	QC-24-01/HAL-SPY-11
Date:	11-Jan-2024	Next Inspection Date:	10-Jul-2024
Type Of Inspection:	VISUAL , THOROUGH EXAMINATION & MAGNETIC PARTICLE INSPECTION	Specification:	ASTM E709 & ASTM E 1444 (2016) ASME V Article 7 (2019)
		UNIT DESCRIPTION:	MUD LOGGING UNIT PAD EYES
		UNIT S/N:	SAP: 1133872 EQ NO: SDL 324
		UNIT DIM :	6.00 M (L) X 2.43 M (W) X 2.65 M (H)
		VISUAL , THOROUGH EXAMINATION	unit fully inspected and found free from deforms, cracks, corrosion & mechanical damage
		MAGNETIC PARTICLE INSPECTION	Welds & forgn areas inspected and found free from cracks and other defects
		FINAL RESULTS	unit found satisfactory and free of defects at the time of inspection
COMMENT:			
Magnetic Particle Inspection With A/C Hand Yoke , Black & White Contrast			

EQUIPMENT DETAILS						PERSON DETAILS		REVIEW BY	
Equipment:	AC/DC Yoke Test Block	Equipment:	Digital Lux Meter WHITE LIGHT	Equipment:	AC/DC Yoke PERMANET HAND MAGNATIC	INSPECTOR NAME:	AIZAZ FARHAT	SENIOR INSPECTOR:	ASHRAF ELSAID
S.No:	1657	S.No:	1932401 2722003	S.No:	PY - 019 PY - 02	QUALIFICATION:		SUPERVISOR:	HANI ALI
Cal Due Date:	14-Feb-2024	Cal Due Date:	16-Feb-2024	Cal Due Date:	14-Feb-2024	LEEA, ASNT LEVEL II MT & PT & VT		CLIENT:	
Black Magnetic Ink Manufacture:	7HF	Magnaflux	Batch No: 220605	EXPIRE DATE:	JULY,2025	STAMP & SIGNATURE:			
Whie Contrast Paint Manufacture:		Magnaflux	Batch No: 220602	EXPIRE DATE:	JUN,2025				
TECHNICAL DETAILS	TECH				WMPT Light Intensity				
	Wet FLUORESCENT Particle Concentration 14 HF		0.1 to 0.4 ml/100 ml		1450 Lux				
	Black Magnetic Ink Concentration 7 HF		1.2 to 2.4 ml/100 ml						
Original - Client Files		Copy - Area Office		QC/FN/MPI/065 Rev.00		DATED 07 NOV 2021			

CERTIFICATION OF VISUAL, THOROUGH EXAMINATION & MAGNETIC PARTICLE INSPECTION			
Client:	HALLIBURTON SPERRY	Report No:	QC-24-01/HAL-SPY-11/CIB
Location:	ZPEC RIG 25	Job Number:	QC-24-01/HAL-SPY-11
Date:	11-Jan-2024	Next Inspection Date:	10-Jul-2024
Type Of Inspection:	VISUAL , THOROUGH EXAMINATION & MAGNETIC PARTICLE INSPECTION	Specification:	ASTM E709 & ASTM E 1444 (2016) ASME V Article 7 (2019)
		UNIT DESCRIPTION:	MUD LOGGING UNIT LADDER
		UNIT S/N:	SAP: 1133872 EQ NO: SDL 324
		UNIT DIM :	6.00 M (L) X 2.43 M (W) X 2.65 M (H)
		VISUAL , THOROUGH EXAMINATION	
MAGNETIC PARTICLE INSPECTION		Welds & forgn areas inspected and found free from cracks and other defects	
FINAL RESULTS		unit found satisfactory and free of defects at the time of inspection	
COMMENT:			
Magnetic Particle Inspection With A/C Hand Yoke , Black & White Contrast			

EQUIPMENT DETAILS						PERSON DETAILS		REVIEW BY	
Equipment:	AC/DC Yoke Test Block	Equipment:	Digital Lux Meter WHITE LIGHT	Equipment:	AC/DC Yoke PERMANET HAND MAGNATIC	INSPECTOR NAME:	AIZAZ FARHAT	SENIOR INSPECTOR:	ASHRAF ELSAID
S.No:	1657	S.No:	1932401 2722003	S.No:	PY - 019 PY - 02	QUALIFICATION:		SUPERVISOR:	HANI ALI
Cal Due Date:	14-Feb-2024	Cal Due Date:	16-Feb-2024	Cal Due Date:	14-Feb-2024	LEEA, ASNT LEVEL II MT & PT & VT		CLIENT:	
Black Magnetic Ink Manufacture:	7HF	Magnaflux	Batch No: 220605	EXPIRE DATE:	JULY,2025	STAMP & SIGNATURE:			
Whie Contrast Paint Manufacture:		Magnaflux	Batch No: 220602	EXPIRE DATE:	JUN,2025				
TECHNICAL DETAILS	TECH				WMPT Light Intensity				
	Wet FLUORESCENT Particle Concentration 14 HF		0.1 to 0.4 ml/100 ml		1450 Lux				
	Black Magnetic Ink Concentration 7 HF		1.2 to 2.4 ml/100 ml						
Original - Client Files		Copy - Area Office		QC/FN/MPI/065 Rev.00		DATED 07 NOV 2021			

**AI TAKAMUL COMPANY FOR ENGINEERING TESTS
AND PROFESSIONAL SAFETY LIMITED**

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	11.01.2024	Date of Report:	11.01.2024	Certificate No:	QC-24-01/HAL-SPY-11/C2
Client Name:	Halliburton SPERRY	Location:	ZPEC RIG 25	Job Number:	QC-24-01/HAL-SPY-11

Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
AT246 AT247 AT248 AT249	04	<p><u>SAFETY PIN BOW SHACKLE</u></p> <p>Size: 1" Grade: 6 Manufacturer: CROSBY S.F: 6:1</p> <p>Location: Attached on MUD LOGGING ID No: 1133872</p>	8.5 TON	N/A	25.09.2023

Reference Standard: BS EN 13889\ HAL DOC: WM-GL-HAL-HSE-0420F & WM-GL-HAL-HSE-0420C REV1

Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?	YES	✓	NO	✓		
	YES	NO			YES	✓	NO	✓		
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO			YES		NO	✓		
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE										
Is the above a defect which is of immediate danger to persons:								YES	NO	✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)								YES by:		
Particulars of any repair, renewal or alteration required to remedy the defect identified above:										
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory										
IS THIS EQUIPMENT SAFE TO OPERATE?								YES	✓	NO

Name of Inspector:	Name of person authenticating this report:	Signature & Stamp:	
AIZAZ FARHAT	ASHRAF ELSAID		
Date of Next Through Examination:	10.07.2024		

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



**AI TAKAMUL COMPANY FOR ENGINEERING TESTS
AND PROFESSIONAL SAFETY LIMITED**

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	11.01.2024	Date of Report:	11.01.2024	Certificate No:	QC-24-01/HAL-SPY-11/C3
Client Name:	Halliburton SPERRY	Location:	ZPEC RIG 25	Job Number:	QC-24-01/HAL-SPY-11

Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
AT224	01	<p><u>FOUR LEGS WIRE ROPE SLING</u> DIM : 5.0 M (L) X 26 MM (DIA) Manufacture: SAFETY MARINE FOS: 5 : 1 IWRC MECHANICALLY SPLICED WITH STEEL FERRULES C\W MASTER LINK ASSEMBLY AT THE TOP HARD EYE BOTH ENDS Attached on MUD LOGGING ID No: 1133872</p>	17.79 TON at 0-45 Angle	N\A	25.09.2023

Reference Standard: BS EN 13889\ HAL DOC: WM-GL-HAL-HSE-0420F & WM-GL-HAL-HSE-0420C REV1

Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓	Was the examination carried out: Within an interval of 6 months?	YES	✓	NO	
					With an interval of 12 months?	YES		NO
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO		In accordance with an examination scheme? After the occurrence of exceptional circumstances?	YES	✓	NO	
					YES		NO	✓
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE								
Is the above a defect which is of immediate danger to persons:					YES		NO	✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)					YES by:			
Particulars of any repair, renewal or alteration required to remedy the defect identified above:								
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory								
IS THIS EQUIPMENT SAFE TO OPERATE?					YES	✓	NO	

Name of Inspector:	Name of person authenticating this report:	Signature & Stamp:	
AIZAZ FARHAT	ASHRAF ELSAID		
Date of Next Through Examination:	10.07.2024		

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

