



Visual & Magnetic Particles Examination Report

Client Name:	Hong Hua Oil& Gas Engineering Services Ltd	Job Number:	QC-HH-01-2024-0009
Date of Examination:	06.01.2024	Location:	HH Rig 029
Certificate No:	QC-HH-01-2024-0009-03		
Serial Number	Description of the examined equipment		Result
HH-ZGF278-19-016	Dog House Lifting Lugs		Pass
Lifting Lugs SN:	2-1 , 2-2 , 2-3 , 2-4	Each Lug SWL:	40 KN
Unit Dim:	L: 10.5 M , W: 2.8 M , H:2.77 M		



NDT Equipment Details

Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-10	Due Date	17-02-2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06-2025
Black Ink	7HF	Batch No:	220605	Due Date	7-1-2025

NDT procedure


Visual and MPI carried out for the above description and found free of surface defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

None

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

None

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Mahmoud Ali	Mohamed Abdalla		05.07.2024

REV: 01 Dated: 20 June 2022

