




CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	20.Jan.2024	Date of Report:	20.Jan.2024	Certificate No:	QC-EMC-01-24-0036-03	
Client Name:	EMC Co.	Location:	Q.C YARD	Job Number:	QC-EMC-01-24-0036	
Serial Number:	QTY	Description		SWL	Date of manufacture if known:	Date of last thorough examination
D213-1187 D213-1158	02	Flat Polyester Woven Webbing Sling Manufacture: Webblon Type: Webbing Sling Material: Polyester Safety Factor : 7:1 Length: 3M Color: yellow Location: Store <div style="text-align: center;">  </div>		Vertical 3000 Kg Chocker 2400 Kg Basket 6000 Kg	22-08-2021	NEW
Reference Standard:		BS EN 1492-1:2000 +A1:2008				
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		Was the examination carried out: Within an interval of 6 months?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/>		With an interval of 12 months?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
				In accordance with an examination scheme?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
				After the occurrence of exceptional circumstances?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE						
Is the above a defect which is of immediate danger to persons:						<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)						YES by:
Particulars of any repair, renewal or alteration required to remedy the defect identified above:						
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory						
IS THIS EQUIPMENT SAFE TO OPERATE?						<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
Name of Inspector:	Name of person authenticating this report:	Signature:				
Mohamed Abdalla	Ashraf El Said					
Date of Next Through Examination:	19.July.2024					

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

