



Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company		Job Number:	QC-DQ-01-2024-0030
Date of Examination:	17.01.2024	Location:	DQ BASE	Certificate No: QC-DQ-01-2024-0030/19
Serial Number	Description of the examined equipment			Result
TB-001	Tools Basket (Lifting Point)			Pass



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-10	Due Date	17-02-2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06-2025
Black Ink	7HF	Batch No:	220605	Due Date	7-1-2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdalla		16.07.2024

REV: 01 Dated: 20 June 2022




CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations


Client Name:	Daqing Drilling Company			Job Number:	QC-DQ-01-2024-0030		
Date of Examination:	17.01.2024	Location:	DQ BASE	Certificate No:	QC-DQ-01-2024-0030/20		
Serial Number:	QTY	Description		SWL	Date of last Thorough examination		
B1011	01	Four Leg Wire Rope Sling Diameter: 13 MM Length: 1.5 M WRC, Mechanically Spliced with Aluminum Ferrules, Connected With Master Link Assembly Hard Eye X Hard Eye. Safety Factor: 5:1 Location: Tools Basket SN: TB-001		4.15 Ton	26.08.2023		
Reference Standard:		BS EN 13414-1,2:2003+A2:2008					
Is this the first examination after Installation or assembly at a new site or location?		☐ YES ☐ NO ☒		Was the examination carried out?		☐ YES ☒ NO ☐	
				Within an interval of 6 months?		☐ YES ☒ NO ☐	
				With an interval of 12 months?		☐ YES ☒ NO ☐	
If the answer to the above question is YES has the equipment been installed correctly?		☐ YES ☐ NO ☐		In accordance with an examination scheme?		☐ YES ☒ NO ☐	
				After the occurrence of exceptional circumstances?		☐ YES ☐ NO ☒	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE							
Is the above a defect which is of immediate danger to persons:						☐ YES ☐ NO ☒	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)						YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:							
Particulars of any tests carried out as part of the examination: (If none state NONE)							
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory							
IS THIS EQUIPMENT SAFE TO OPERATE?						☐ YES ☒ NO ☐	
ASNT Level II Inspector Name:		Authenticating This Report:		Signature & Stamp:		Date of Next Through Examination:	
Khaled Mahmoud		Mohamed Abdalla				16.07.2024	

REV: 01 Dated: 20 June 2022




CERTIFICATE OF THOROUGH EXAMINATION


This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Daqing Drilling Company			Job Number:	QC-DQ-01-2024-0030
Date of Examination:	17.01.2024	Location:	DQ BASE	Certificate No:	QC-DQ-01-2024-0030/21
Serial Number:	QTY	Description	SWL	Date of last Thorough examination	
74-47 34 TH	03	SAFETY PIN BOW SHACKLE Size: 5/8" Grade: 6 Manufacture: CROSBY  Safety Factor: 6:1 Location: Tools Basket SN: TB-001	3.25 TON	26.08.2023	
Reference Standard:	BS EN 13889				
Is this the first examination after Installation or assembly at a new site or location?		☐ YES ☒ NO ☒		Was the examination carried out?	
				☒ Within an interval of 6 months? ☒ Within an interval of 12 months? ☒ In accordance with an examination scheme? ☒ After the occurrence of exceptional circumstances?	
If the answer to the above question is YES has the equipment been installed correctly?		☐ YES ☒ NO ☒		☒ YES ☒ NO ☒	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				☒ YES ☒ NO ☒	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				☒ YES ☒ NO ☒	
ASNT Level II Inspector Name:	Authenticating This Report:		Signature & Stamp:	Date of Next Through Examination:	
Khaled Mahmoud	Mohamed Abdalla			16.07.2024	

REV: 01 Dated: 20 June 2022


CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Daqing Drilling Company			Job Number:	QC-DQ-01-2024-0030
Date of Examination:	17.01.2024	Location:	DQ BASE	Certificate No:	QC-DQ-01-2024-0030/22
Serial Number:	QTY	Description	SWL	Date of last Thorough examination	
F60	01	SAFETY PIN BOW SHACKLE Size: 5/8" Grade: 6 Manufacture: J&L  Safety Factor: 6:1 Location: Tools Basket SN: TB-001	3.25 TON	26.08.2023	
Reference Standard:	BS EN 13889				
Is this the first examination after Installation or assembly at a new site or location?		☐ YES ☒ NO ☒	Was the examination carried out? Within an interval of 6 months? ☐ YES ☒ NO ☒		☐ YES ☒ NO ☒
If the answer to the above question is YES has the equipment been installed correctly?		☐ YES ☒ NO ☒	With an interval of 12 months? ☐ YES ☒ NO ☒		☐ YES ☒ NO ☒
			In accordance with an examination scheme? ☐ YES ☒ NO ☒		☐ YES ☒ NO ☒
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:					☐ YES ☒ NO ☒
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)					YES by:
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?					☐ YES ☒ NO ☒
ASNT Level II Inspector Name:	Authenticating This Report:		Signature & Stamp:	Date of Next Through Examination:	
Khaled Mahmoud	Mohamed Abdalla			16.07.2024	

REV: 01 Dated: 20 June 2022




CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Daqing Drilling Company			Job Number:	QC-DQ-01-2024-0030		
Date of Examination:	17.01.2024	Location:	DQ BASE	Certificate No:	QC-DQ-01-2024-0030/23		
Serial Number:	QTY	Description		SWL	Date of last Thorough examination		
B1021	01	Single Leg Wire Rope Sling Diameter: 16 MM Length: 3 M IWRC, Mechanically Spliced with Aluminum Ferrules, Hard Eye X Hard Eye. Safety Factor: 5:1 Location: Tools Basket SN: TB-001		3 Ton	26.08.2023		
Reference Standard:		BS EN 13414-1,2:2003+A2:2008					
Is this the first examination after Installation or assembly at a new site or location?		☐ YES ☐ NO ☒		Was the examination carried out?		☐ YES ☒ NO ☐	
				Within an interval of 6 months?		☐ YES ☐ NO ☒	
				With an interval of 12 months?		☐ YES ☒ NO ☐	
If the answer to the above question is YES has the equipment been installed correctly?		☐ YES ☐ NO ☐		In accordance with an examination scheme?		☐ YES ☒ NO ☐	
				After the occurrence of exceptional circumstances?		☐ YES ☐ NO ☒	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE							
Is the above a defect which is of immediate danger to persons:						☐ YES ☐ NO ☒	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)						YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:							
Particulars of any tests carried out as part of the examination: (If none state NONE)							
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory							
IS THIS EQUIPMENT SAFE TO OPERATE?						☐ YES ☒ NO ☐	
ASNT Level II Inspector Name:		Authenticating This Report:		Signature & Stamp:		Date of Next Thorough Examination:	
Khaled Mahmoud		Mohamed Abdalla				16.07.2024	

REV: 01 Dated: 20 June 2022


CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Daqing Drilling Company			Job Number:	QC-DQ-01-2024-0030		
Date of Examination:	17.01.2024	Location:	DQ BASE	Certificate No:	QC-DQ-01-2024-0030/24		
Serial Number:	QTY	Description		SWL	Date of last Thorough examination		
W 377	01	Single Leg Wire Rope Sling Diameter: 22 MM Length: 1.5 M IWRC, Mechanically Spliced with Aluminum Ferrules, Soft Eye X Soft Eye. Safety Factor: 5:1 Location: Tools Basket SN: TB-001		6 Ton	26.08.2023		
Reference Standard:		BS EN 13414-1,2:2003+A2:2008					
Is this the first examination after Installation or assembly at a new site or location?		☐ YES ☐ NO ☒		Was the examination carried out?		☐ YES ☒ NO ☐	
				Within an interval of 6 months?		☐ YES ☐ NO ☒	
				With an interval of 12 months?		☐ YES ☒ NO ☐	
If the answer to the above question is YES has the equipment been installed correctly?		☐ YES ☐ NO ☐		In accordance with an examination scheme?		☐ YES ☒ NO ☐	
				After the occurrence of exceptional circumstances?		☐ YES ☐ NO ☒	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE							
Is the above a defect which is of immediate danger to persons:						☐ YES ☐ NO ☒	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)						YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:							
Particulars of any tests carried out as part of the examination: (If none state NONE)							
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory							
IS THIS EQUIPMENT SAFE TO OPERATE?						☐ YES ☒ NO ☐	
ASNT Level II Inspector Name:		Authenticating This Report:		Signature & Stamp:		Date of Next Thorough Examination:	
Khaled Mahmoud		Mohamed Abdalla				16.07.2024	

REV: 01 Dated: 20 June 2022




CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Daqing Drilling Company			Job Number:	QC-DQ-01-2024-0030
Date of Examination:	17.01.2024	Location:	DQ BASE	Certificate No:	QC-DQ-01-2024-0030/25
Serial Number:	QTY	Description	SWL	Date of last Thorough examination	
B1018	01	Single Leg Wire Rope Sling Diameter: 22 MM Length: 2.35 M IWRC, Mechanically Spliced with Aluminum Ferrules, Hard Eye X Hard Eye. Safety Factor: 5:1 Location: Tools Basket SN: TB-001	5.65 Ton	26.08.2023	
Reference Standard:		BS EN 13414-1,2:2003+A2:2008			
Is this the first examination after Installation or assembly at a new site or location?		☐ YES ☒ NO ☒	Was the examination carried out?		☐ YES ☒ NO ☒
			Within an interval of 6 months?		☐ YES ☒ NO ☒
			With an interval of 12 months?		☐ YES ☒ NO ☒
If the answer to the above question is YES has the equipment been installed correctly?		☐ YES ☒ NO ☒	In accordance with an examination scheme?		☐ YES ☒ NO ☒
			After the occurrence of exceptional circumstances?		☐ YES ☒ NO ☒
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:					☐ YES ☒ NO ☒
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)					YES by:
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?					☐ YES ☒ NO ☒
ASNT Level II Inspector Name:	Authenticating This Report:		Signature & Stamp:	Date of Next Thorough Examination:	
Khaled Mahmoud	Mohamed Abdalla			16.07.2024	

REV: 01 Dated: 20 June 2022



CERTIFICATE OF THOROUGH EXAMINATION


This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Daqing Drilling Company		Job Number:	QC-DQ-01-2024-0030
Date of Examination:	17.01.2024	Location:	DQ BASE	Certificate No: QC-DQ-01-2024-0030/26
Serial Number:	QTY	Description	SWL	Date of last Thorough examination
B1019	01	Single Leg Wire Rope Sling Diameter: 22 MM Length: 2.7 M IWRC, Mechanically Spliced with Aluminum Ferrules, Hard Eye X Hard Eye. Safety Factor: 5:1 Location: Tools Basket SN: TB-001	5.65 Ton	26.08.2023
Reference Standard:		BS EN 13414-1,2:2003+A2:2008		
Is this the first examination after Installation or assembly at a new site or location?		☐ YES ☒ NO ☒	Was the examination carried out?	
			☒ Within an interval of 6 months? ☒ Within an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		☐ YES ☒ NO ☒	In accordance with an examination scheme?	
			☒ After the occurrence of exceptional circumstances?	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE				
Is the above a defect which is of immediate danger to persons:			YES	☒ NO ☒
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)			YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:				
Particulars of any tests carried out as part of the examination: (If none state NONE)				
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory				
IS THIS EQUIPMENT SAFE TO OPERATE?			YES	☒ NO ☒
ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Thorough Examination:	
Khaled Mahmoud	Mohamed Abdalla		16.07.2024	

REV: 01 Dated: 20 June 2022


CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Daqing Drilling Company		Job Number:	QC-DQ-01-2024-0030	
Date of Examination:	17.01.2024	Location:	DQ BASE	Certificate No:	QC-DQ-01-2024-0030/27
Serial Number:	QTY	Description	SWL	Date of last Thorough examination	
23 28 12-13	03	SAFETY PIN BOW SHACKLE Size: 7/8" Grade: 6 Manufacture: CROSBY  Safety Factor: 6:1 Location: Tools Basket SN: TB-001	6.5 TON	26.08.2023	
Reference Standard:		BS EN 13889			
Is this the first examination after Installation or assembly at a new site or location?		☐ YES ☐ NO ☒	Was the examination carried out? Within an interval of 6 months? ☐ YES ☒ NO ☐		☐ YES ☒ NO ☐
If the answer to the above question is YES has the equipment been installed correctly?		☐ YES ☐ NO ☐	With an interval of 12 months? ☐ YES ☒ NO ☐		☐ YES ☒ NO ☐
		☐ YES ☐ NO ☐	In accordance with an examination scheme? ☐ YES ☒ NO ☐		☐ YES ☒ NO ☐
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:					☐ YES ☐ NO ☒
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)					YES by:
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?					☐ YES ☒ NO ☐
ASNT Level II Inspector Name:	Authenticating This Report:		Signature & Stamp:	Date of Next Through Examination:	
Khaled Mahmoud	Mohamed Abdalla			16.07.2024	

REV: 01 Dated: 20 June 2022