

AI TAKAMUL COMPANY FOR ENGINEERING TESTS AND PROFESSIONAL SAFETY LIMITED

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF INSPECTION AFTER REPAIR FOR LIFTING SUB (7 5/8 REG)

Client Name:	DAQING DRILLING COMPANY	Report No.:	QC-ATS-WSH-01-24-0020-X01
Acceptance Criteria:	<input checked="" type="checkbox"/> API SPEC 7-2	Date Of Inspection:	23-01-2024
Work Location:	ABERDEEN WORKSHOP	Rig Name	DQ-37
Test Equipment & Consumable Details			
WHITE CONTRAST WCP-2	Batch #: 220602 Manufacture: Magnaflux Exp Date: JUN,2025	TECHNICAL DETAILS	Wet Visible Continuous
BLACK INK 7HF	Batch#: 220605 Manufacture: Magnaflux Exp Date: JULY.2025	COIL(1200 AMP-TURNS/IN	SR# SC-22713 Cal. 17.AUG.2023 Cal Due 16.FEB.2024
FLUORESCENT 14HF	Batch #: 220306 Manufacture: Magnaflux Exp Date: March.2025	A.C HAND YOKE	SR# 201504053 Cal 17.AUG.2023 Cal Due 16.FEB.2024
INTENSITY METER	SR# R.043943 Cal.15.AUG.2023 Cal Due 14.FEB.2024	UV BLACK LIGHT	SR# 1900084 Cal. 17.AUG.2023 Cal Due 16.FEB.2024
LEAD GAGE	SR# AH07KF0027 GAEMAKER LG-5003 CAL.Date. 15.AUG.2023 CAL Due Date 14.FEB.2024	THREAD PROFILE GAGE	SR# 21336 CAL.Date.15.AUG. 2023 CAL Due Date.14. AUG. 2024 SR# 21335 CAL.Date.17.AUG.2023 CAL Due Date. 16.AUG.2024
Magnetic Partical Concentration 7 HF	1.2 TO 2.4 ML/100 ML	WMPT Light Intensity	3500 Lux
Magnetic particle concentration flourcent 14 HF	0.1 TO 0.4 ML/100 ML	UV LIGHT INTENSITY:	2850 μw/cm ²
Magnetism Direction (Longitudinal)			
METHODOLOGY:	<ul style="list-style-type: none"> • Through Visual Inspection • Dimensional 3 • MPI Inspection with Ultraviolet Light *Lead Gauging, Taper Gauging & Thread Profile Gauging. 		

Serial No.	Description	Connection		Result Inspection			Dimensional Inspection																
		Pin	Box	Pin	Box	Body	Pin					Box					Body						
							OD(In)	ID(In)	SRG □(In)	SRG W □(In)	Pin □(In)	Bevel □(In)	OD(In)	CB □(In)	CB □(In)	BB □(In)	BBL □(In)	Bevel □(In)	Tongspac e (In) □	Box Lth (In) □	Overall □(In)		
11919	LIFTING SUB	7 5/8 REG	-	Acc.	-	-	9"	2 7/8"	-	-	5 1/4"	8 5/8"	-	-	-	-	-	-	-	-	11 1/4"	-	-
Conclusion :		<p>■ (01) The above Mentioned LIFTING SUB was found "Acceptable" from Pin Connection After Repair at time of Inspection Ready to use.</p>																					

OD □	Outside Diameter	ID □	Inside Diameter	SRG □	Stress Relief Groove	CB □	Counter Bore	BB	Bore Back	FB	Float Bore
EGR	Elevator Groove Recess	SGR	Slip Groove Recess	CR	Crack	B	Bent	PC	Premium Class	RF	Reface
GT	Galled Thread	TP	Thread Pitting	SP	Seal Pitting	TD	Thread Damage	SD	Seal Damage	M	Mashed
1	100 % Coating	2	99-71 % Coating	3	70-40 % Coating	4	Up to 40 %	5	Nil	WT	Wall Thickness
Colors Code:		White	No Defects	Red	Crack or Extreme	Blue	Damage	Green	Seal Damage	Yellow	ACFM

Inspector Name:		Review By					
Qualification:		Senior Inspector:	RAO SOHAIL	Supervisor:	WAQAS	Customer Name:	
Signature:						Customer Signature:	
Original - Client Files		Copy - Area Office		QC/FN/DJ-PB/029		Rev.00 dated 07.Nov2021	

