




CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Aberdeen Technical Service CO.			Job Number:	QC-ATS-01-2024-0002
Date of Examination:	03.01.2024	Location:	ATS Yard	Certificate No:	QC-ATS-01-2024-0002-15
Serial Number:	QTY	Description		SWL	Date of last thorough examination
L9034 L9035 L9036 L9037 L9038 L9039 L9040	07	SAFETY PIN BOW SHACKLE MANUFACTURER: GT Size: 1 3/4" Grade: 6 Safety Factor: 6:1		25 TON	17.07.2023
Reference Standard:	BS EN 13889-2003+A1:2008				
Is this the first examination after Installation or assembly at a new site or location?		YES	NO	√	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?
If the answer to the above question is YES has the equipment been installed correctly?		YES	NO	√	YES
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect which is of immediate danger to persons:		YES	NO	√	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)		YES by:			
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?					YES

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Mohamed Abdalla	Ashraf El-Said		02.07.2024

REV: 01 Dated: 20 June 2022

