

AI TAKAMUL COMPANY FOR ENGINEERING TESTS AND PROFESSIONAL SAFETY LIMITED

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	02-01-2024	Date of Report:	02-01-2024	Certificate No:	QC-2024-0733-01
Client Name:	Black Gold Gulf. Co	Location:	BGG Yard	Job Number:	QC-2024-0733
Serial Number:	QTY	Description	SWL	Manufacturer	Date of last thorough examination
S1 S2 S3 S4	04	<u>Single Leg Wire Rope Sling.</u> Diameter: 22 MM Length: 2.10 M Safety Factor: 5:1 IWRC, Mechanically Spliced With Aluminum Ferrules, Hard Eye X Hard Eye.	5.65 TON	Safety Marine	NEW
Reference Standard:	BS EN 13414-1:2003+A2:2008				
Is this the first examination after Installation or assembly at a new site or location?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		Was the examination carried out: Within an interval of 6 months? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> With an interval of 12 months? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> In accordance with an examination scheme? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> After the occurrence of exceptional circumstances? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
If the answer to the above question is YES has the equipment been installed correctly?		YES <input type="checkbox"/> NO <input type="checkbox"/>			
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
Name of Inspector:	Name of person authenticating this report:		Signature & Stamp:		
Mahmoud Ali	Ashraf El Said				
Date of Next Through Examination:	01-07-2024				

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



AI TAKAMUL COMPANY FOR ENGINEERING TESTS AND PROFESSIONAL SAFETY LIMITED

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	02-01-2024	Date of Report:	02-01-2024	Certificate No:	QC-24-07/BGG-19/C1
Client Name:	BLACK GOLD GULF CO.	Location:	BLACK GOLD YARD	Job Number:	QC-24-07/BGG-19
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
M004842-5/3 M004842-5/2 M004831/7-1 M004831/7-2 M004842-8/2 M004831/7-4 M004842-5/2 M004842-5/1 M004842-8/1 M004831-17/3	10	<u>SAFETY PIN BOW SHACKLE</u> MANUFACTURER: CROSBY SIZE: 3/4 " GRADE: 6 FOS: 6:1	4 ¾ TON	N/A	N/A
Reference Standard:	BS EN 13889: 2003 + A1: 2008				
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> <input type="checkbox"/> NO		Was the examination carried out: Within an interval of 6 months? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO Within an interval of 12 months? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO In accordance with an examination scheme? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO After the occurrence of exceptional circumstances? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input type="checkbox"/> NO N/A			
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				YES	<input checked="" type="checkbox"/> NO <input type="checkbox"/>
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				N/A	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				YES	<input checked="" type="checkbox"/> NO <input type="checkbox"/>
Name of Inspector:	Name of person authenticating this report:		Signature & Stamp:		
AIAZ FARHAT	ASHRAF ELSAID				
Date of Next Thorough Examination:	01-07-2024				

REV: 00 Dated: 30 May 2021

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



AI TAKAMUL COMPANY FOR ENGINEERING TESTS AND PROFESSIONAL SAFETY LIMITED

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	02-01-2024	Date of Report:	02-01-2024	Certificate No:	QC-2024-0733-02
Client Name:	Black Gold Gulf. Co	Location:	BGG Yard	Job Number:	QC-2024-0733
Serial Number:	QTY	Description	SWL	Manufacturer	Date of last thorough examination
S5 S6	02	<u>Two Leg Wire Rope Sling</u> Diameter: 13 MM Length: 1.80 M Safety Factor: 5:1 IWRC, Mechanically Spliced With Aluminum Ferrules, Connected With Top Master Link , Hard Eye X Hard Eye.	2.80 TON	Safety Marine	NEW
Reference Standard:	BS EN 13414-1:2003+A2:2008				
Is this the first examination after Installation or assembly at a new site or location?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		Was the examination carried out: Within an interval of 6 months? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> With an interval of 12 months? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> In accordance with an examination scheme? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> After the occurrence of exceptional circumstances? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
If the answer to the above question is YES has the equipment been installed correctly?		YES <input type="checkbox"/> NO <input type="checkbox"/>			
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
Name of Inspector:	Name of person authenticating this report:		Signature & Stamp:		
Mahmoud Ali	Ashraf El Said				
Date of Next Through Examination:	01-07-2024				

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



AI TAKAMUL COMPANY FOR ENGINEERING TESTS AND PROFESSIONAL SAFETY LIMITED

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	02-01-2024	Date of Report:	02-01-2024	Certificate No:	QC-24-07/BGG-19/C2
Client Name:	BLACK GOLD GULF CO.	Location:	BLACK GOLD YARD	Job Number:	QC-2407/BGG-19
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
M004842-6/4 M004842-8/8 M004831-17/4 M004842-8/4 M004831/23-3 M004831-28/1 M004842-6/2 ANL5712	08	<u>SAFETY PIN BOW SHACKLE</u> MANUFACTURER: CROSBY SIZE: 3/4 " GRADE: 6 FOS: 6:1	4 ¾ TON	N/A	N/A
Reference Standard:	BS EN 13889: 2003 + A1: 2008				
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> <input type="checkbox"/> NO		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> N/A		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> <input type="checkbox"/> NO <input type="checkbox"/>	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons: YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>					
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>					
Name of Inspector:	Name of person authenticating this report:		Signature & Stamp		
AIAZ FARHAT	ASHRAF ELSAID				
Date of Next Through Examination:	01-07-2024				

REV: 00 Dated: 30 May 2021

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



**AI TAKAMUL COMPANY FOR ENGINEERING TESTS
AND PROFESSIONAL SAFETY LIMITED**

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	02-01-2024	Date of Report:	02-01-2024	Certificate No:	QC-2024-0733-03
Client Name:	Black Gold Gulf. Co	Location:	BGG Yard	Job Number:	QC-2024-0733
Serial Number:	QTY	Description	SWL	Manufacturer	Date of last thorough examination
S7 S8 S9 S10	04	<u>Two Leg Wire Rope Sling</u> Diameter: 13 MM Length: 2.14 M Safety Factor: 5:1 IWRC, Mechanically Spliced With Aluminum Ferrules, Connected With Top Master Link , Hard Eye X Hard Eye.	2.80 TON	Safety Marine	NEW
Reference Standard:		BS EN 13414-1:2003+A2:2008			
Is this the first examination after Installation or assembly at a new site or location?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		Was the examination carried out: Within an interval of 6 months? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> With an interval of 12 months? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> In accordance with an examination scheme? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> After the occurrence of exceptional circumstances? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
If the answer to the above question is YES has the equipment been installed correctly?		YES <input type="checkbox"/> NO <input type="checkbox"/>			
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
Name of Inspector:	Name of person authenticating this report:		Signature & Stamp:		
Mahmoud Ali	Ashraf El Said				
Date of Next Thorough Examination:	01-07-2024				

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



**AI TAKAMUL COMPANY FOR ENGINEERING TESTS
AND PROFESSIONAL SAFETY LIMITED**

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	02-01-2024	Date of Report:	02-01-2024	Certificate No:	QC-24-07/BGG-19/C3
Client Name:	BLACK GOLD GULF CO.	Location:	BLACK GOLD YARD	Job Number:	QC-24-07/BGG-19
Serial Number:	QTY	Description		SWL	Date of manufacture if known:
L2112	01	<u>SAFETY PIN BOW SHACKLE</u> MANUFACTURER: KF SIZE: 3/4 " GRADE: 6 FOS: 6:1		4 ¾ TON	N/A
Reference Standard:		BS EN 13889: 2003 + A1: 2008			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		In accordance with an examination scheme?	
		N/A		After the occurrence of exceptional circumstances?	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect which is of immediate danger to persons:					
YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>					
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)					
N/A					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?					
YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>					
Name of Inspector:	Name of person authenticating this report:		Signature & Stamp		
AIAZ FARHAT	ASHRAF ELSAID				
Date of Next Through Examination:	01-07-2024				

REV: 00 Dated: 30 May 2021

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



AI TAKAMUL COMPANY FOR ENGINEERING TESTS AND PROFESSIONAL SAFETY LIMITED

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	02-01-2024	Date of Report:	02-01-2024	Certificate No:	QC-24-07/BGG-19/C4
Client Name:	BLACK GOLD GULF CO.	Location:	BLACK GOLD YARD	Job Number:	QC-24-07/BGG-19
Serial Number:	QTY	Description		SWL	Date of manufacture if known:
L4625	01	<u>SAFETY PIN BOW SHACKLE</u> MANUFACTURER: GT SIZE: 3/4 " GRADE: 6 FOS: 6:1		4 ¾ TON	N/A
Reference Standard:		BS EN 13889: 2003 + A1: 2008			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		Was the examination carried out:	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
		N/A		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons: <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO					
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO					
Name of Inspector:	Name of person authenticating this report:		Signature & Stamp		
AIAZ FARHAT	ASHRAF ELSAID				
Date of Next Through Examination:	01-07-2024				

REV: 00 Dated: 30 May 2021

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



AI TAKAMUL COMPANY FOR ENGINEERING TESTS AND PROFESSIONAL SAFETY LIMITED

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	02-01-2024	Date of Report:	02-01-2024	Certificate No:	QC-24-07/BGG-19/C5
Client Name:	BLACK GOLD GULF CO.	Location:	BLACK GOLD YARD	Job Number:	QC-24-07/BGG-19
Serial Number:	QTY	Description		SWL	Date of manufacture if known:
F00-130713-31 88A 88B 88C 88D 140415-528 A078157/4 52A	08	<u>SAFETY PIN BOW SHACKLE</u> MANUFACTURER: GP SIZE: 7/8 " GRADE: 6 FOS: 6:1		6 ½ TON	N/A
Reference Standard:		BS EN 13889: 2003 + A1: 2008			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> <input type="checkbox"/> NO		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input type="checkbox"/> NO		In accordance with an examination scheme?	
		N/A		After the occurrence of exceptional circumstances?	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect which is of immediate danger to persons: YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>					
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>					
Name of Inspector:	Name of person authenticating this report:		Signature & Stamp		
AIAZ FARHAT	ASHRAF ELSAID				
Date of Next Through Examination:	01-07-2024				

REV: 00 Dated: 30 May 2021

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Black Gold Gulf Oil and Gas Services Co. Ltd Basra Iraq	Location:	Black Gold Yard	Certificate No:	QC-BG-MPI-0576-087
Examination Date	02-01-2024	Due Date	01-07-2024	Job Number:	QC-BG-2024-0576

Serial Number:	QTY	Item Description	SWL	Date of manufacture if known:	Date of last thorough examination
SV0GES 276 SV0GES 277 SV0GES 158	03	SINGLE-LEG WIRE ROPE SLING Dim: 16 mm X 10 M FOS: 5:1 FC, Mechanically Spliced with Aluminum Ferrule with Soft Eyes at Single Ends Location: Store	3 Ton	Nil	Nil

Reference Standard:	BS EN 13414-1:2003+A2:2008 ASME B30.9-2021
----------------------------	--

Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓	Was the examination carried out: Within an interval of 6 months?	YES	NO	✓
				With an interval of 12 months?	YES	NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO		In accordance with an examination scheme?	YES	NO	
	N/A			After the occurrence of exceptional circumstances?	YES	NO	✓

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) **NONE**

Is the above a defect that is of immediate danger to persons: YES ☐ NO ☒



Is the above a defect that is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal, or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: (If none state NONE)

The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory

IS THIS EQUIPMENT SAFE TO OPERATE?	YES	✓	NO	
---	-----	---	----	--

Name of Inspector:	Name of person authenticating this report:	Signature & Stamp:	
Aizaz Farhat	M Abdullah		
CERTIFICATION ASNT LEVEL II VT,MT,PT,UT & LEEA I-II			

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.





CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Black Gold Gulf Oil and Gas Services Co. Ltd Basra Iraq	Location:	Black Gold Yard	Certificate No:	QC-BG-MPI-0576-088
Examination Date	02-01-2024	Due Date	01-07-2024	Job Number:	QC-BG-2024-0576

Serial Number:	QTY	Item Description	SWL	Date of manufacture if known:	Date of last thorough examination
SV0GES 278 SV0GES 279	02	SINGLE-LEG WIRE ROPE SLING Dim: 20 mm X 7 M FOS: 5:1 FC, Mechanically Spliced with Aluminum Ferrule with Soft Eyes at Single Ends Location: Store	6 Ton	Nil	Nil
Reference Standard:		BS EN 13414-1:2003+A2:2008 ASME B30.9-2021			

Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? By an examination scheme? After the occurrence of exceptional circumstances?	YES	✓	NO	✓
					YES		NO	✓
					YES	✓	NO	
					YES		NO	✓
If the answer to the above question is YES has the equipment been installed correctly? <div style="text-align: center;">N/A</div>								
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE								
Is the above a defect that is of immediate danger to persons:					YES		NO	✓
Is the above a defect that is not yet but could become a danger to persons (If YES state the date by when)					N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:								
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory								
IS THIS EQUIPMENT SAFE TO OPERATE?					YES	✓	NO	

Name of Inspector:	Name of person authenticating this report:	Signature & Stamp:	
Aizaz Farhat	M Abdullah		
CERTIFICATION ASNT LEVEL II VT, MT,PT, UT & LEEA I-II			



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Black Gold Gulf Oil and Gas Services Co. Ltd Basra Iraq	Location:	Black Gold Yard	Certificate No:	QC-BG-MPI-0576-089
Examination Date	02-01-2024	Due Date	01-07-2024	Job Number:	QC-BG-2024-0576
Serial Number:	QTY	Item Description		SWL	Date of manufacture if known:
SV0GES 280 SV0GES 281	02	SINGLE-LEG WIRE ROPE SLING Dim: 24 mm X 2.6 M FOS: 5:1 FC, Mechanically Spliced with Aluminum Ferrule with Hard Eye at Soft Eye Location: Store		7 Ton	Nil
Reference Standard:		BS EN 13414-1:2003+A2:2008 ASME B30.9-2021			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> <input type="checkbox"/>		Was the examination carried out:	
				Within an interval of 6 months?	
				Within an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/>		By an examination scheme?	
		N/A		After the occurrence of exceptional circumstances?	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect that is of immediate danger to persons:				<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input type="checkbox"/>
Is the above a defect that is not yet but could become a danger to persons (If YES state the date by when)				N/A	
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input type="checkbox"/>
Name of Inspector:	Name of person authenticating this report:		Signature & Stamp:		
Aizaz Farhat	M Abdullah				
CERTIFICATION ASNT LEVEL II VT, MT,PT, UT & LEEA I-II					

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Black Gold Gulf Oil and Gas Services Co. Ltd Basra Iraq	Location:	Black Gold Yard	Certificate No:	QC-BG-MPI-0576-090
Examination Date	02-01-2024	Due Date	01-07-2024	Job Number:	QC-BG-2024-0576

Serial Number:	QTY	Item Description	SWL	Date of manufacture if known:	Date of last thorough examination
SV0GES 665	01	TWO-LEG WIRE ROPE SLING Dim: 18 mm X 4.4 M FOS: 5:1 FC, Mechanically Spliced with Aluminum Ferrule with Hard Eyes at Both Ends with Link & Swivels 3.3 Ton Location: Store	5 Ton	Nil	Nil
Reference Standard:		BS EN 13414-1:2003+A2:2008 ASME B30.9-2021			

Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓	Was the examination carried out: Within an interval of 6 months?	YES	NO	✓
				With an interval of 12 months?	YES	NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO		By an examination scheme?	YES	NO	
	N/A			After the occurrence of exceptional circumstances?	YES	NO	✓

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) **NONE**



Is the above a defect that is of immediate danger to persons: YES NO ✓

Is the above a defect that is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal, or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: (If none state NONE)
 The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory

IS THIS EQUIPMENT SAFE TO OPERATE? YES ✓ NO

Name of Inspector:	Name of person authenticating this report:	Signature & Stamp:	
Aizaz Farhat	M Abdullah		
CERTIFICATION ASNT LEVEL II VT, MT,PT, UT & LEEA I-II			

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations



Client Name:	Black Gold Gulf Oil and Gas Services Co. Ltd Basra Iraq	Location:	Black Gold Yard	Certificate No:	QC-BG-MPI-0576-091
Examination Date	02-01-2024	Due Date	01-07-2024	Job Number:	QC-BG-023-0576

Serial Number:	QTY	Item Description	SWL	Date of manufacture if known:	Date of last thorough examination
24 - 25	01	TWO-LEG WIRE ROPE SLING Dim: 18 mm X 3.2 M FOS: 5:1 FC, Mechanically Spliced with Aluminum Ferrule with Hard Eyes at Both Ends & with Link Location: Store	5 Ton	Nil	Nil

Reference Standard:	BS EN 13414-1:2003+A2:2008 ASME B30.9-2021
----------------------------	--

Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓	Was the examination carried out: Within an interval of 6 months?	YES	NO	✓
				With an interval of 12 months?	YES	NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO		By an examination scheme?	YES	NO	
	N/A			After the occurrence of exceptional circumstances?	YES	NO	✓

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE						
Is the above a defect that is of immediate danger to persons:			YES	NO	✓	
Is the above a defect that is not yet but could become a danger to persons (If YES state the date by when)			N/A			
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:						
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory						
IS THIS EQUIPMENT SAFE TO OPERATE?				YES	NO	✓

Name of Inspector:	Name of person authenticating this report:	Signature & Stamp:	
Aizaz Farhat	M Abdullah		
CERTIFICATION ASNT LEVEL II VT, MT,PT, UT & LEEA I-II			

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

