



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

| | | | | | | |
|-----------------------------|-------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------|------------------------|----------------------------|------------------------------------------|
| Client Name: | DAQING DRILLING COMPANY, Iraq | Rig & Location: | DQ-037 / RU-599 | Certificate No: | QC-02-24-0061-004 | |
| Date of Examination: | 19-Feb-2024 | Date of Report: | 19-Feb-2024 | Job Number: | DQDC-RUM-QC-OPS-2024021701 | |
| Serial Number: | QTY | Description: | | SWL | Manufacture: | Date of Last Thorough Examination |
| W2306050045 | 01 | <p style="text-align: center;"><u>POLYESTER FLATE WOVEN WEBBING SLING</u></p> <p>Length: 8 M Dia: 5 in Color: Red Safety Factor: 7:1 Location: Rig Sling Store</p> | | 5000 Kg | J & L June-2023 | Aug-2023 |
| Reference Standard: | | BS EN 1492-1:2000+A1:2008 | | | | |

| | | | | | | | |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|----|---|-------------------------------------------------------------------------------------------------|---------|----|---|
| Is this the first examination after Installation or assembly at a new site or location? | YES | NO | ✓ | Was the examination carried out: Within an interval of 6 months? | YES | NO | ✓ |
| | | | | With an interval of 12 months? | YES | NO | ✓ |
| If the answer to the above question is YES has the equipment been installed correctly? | YES | NO | ✓ | In accordance with an examination scheme? After the occurrence of exceptional circumstances? | YES | NO | ✓ |
| Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE | | | | | | | |
| Is the above a defect which is of immediate danger to persons: | | | | | YES | NO | ✓ |
| Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) | | | | | YES by: | | |
| Particulars of any repair, renewal or alteration required to remedy the defect identified above: | | | | | | | |
| Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory | | | | | | | |
| IS THIS EQUIPMENT SAFE TO OPERATE? | | | | | YES | NO | ✓ |

| | | | |
|------------------------------------------|---------------------------------------------------|-------------------------------|--|
| Name of Inspector: | Name of person authenticating this report: | Signature & Stamp: | |
| Syed Aamir Ali | Aizaz Farhat | | |
| Date of Next Through Examination: | 18-Aug-2024 | | |

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

