



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	DAQING DRILLING COMPANY, Iraq	Rig & Location:	DQ-037 / RU-599	Certificate No:	QC-02-24-0061-007	
Date of Examination:	19-Feb-2024	Date of Report:	19-Feb-2024	Job Number:	DQDC-RUM-QC-OPS-2024021701	
Serial Number:	QTY	Description:		WLL	Manufacture:	Date of Last Thorough Examination
99	01	BOW SHACKLE With HEX Nut & Bolt & Safety Cotter Pin: SIZE: 5/8" GRADE: 6 F.O.S: 6:1 Location: Rig Site HP Line:		3 1/4 Ton	HK	Aug-2023
Reference Standard:		BS EN 13889:2003 + A1:2008				

Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓	Was the examination carried out: Within an interval of 6 months?	YES	✓	NO
				With an interval of 12 months?	YES		NO
If the answer to the above question is YES has the equipment been installed correctly?	YES	✓	NO	In accordance with an examination scheme?	YES	✓	NO
				After the occurrence of exceptional circumstances?	YES		NO
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE							
Is the above a defect which is of immediate danger to persons:					YES		NO
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)					YES by:		
Particulars of any repair, renewal or alteration required to remedy the defect identified above:							
Particulars of any tests carried out as part of the examination: (If none state NONE)							
The Subject Items Were Inspected Visually and Dimensionally Where No Signs of Defects Were Observed at The Time of Inspection and Found Satisfactory							
IS THIS EQUIPMENT SAFE TO OPERATE?					YES	✓	NO

Name of Inspector:	Name of person authenticating this report:	Signature & Stamp:	
Syed Aamir Ali	Aizaz Farhat		
Date of Next Thorough Examination:	18-Aug-2024		

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

