


# Certificate of Calibration

Al Takamul Yard, North Rumailah, South IRAQ

• Phone : +964 7810009138 • www.qualitycontrol-iraq.com • E-mail: op@qualitycontrol-iraq.com

**Date of Issue:** January 30, 2024

Page 1 of 1

REQUEST NUMBER	By Mail	APPROVED	QC
JOB NUMBER	QC/JN/24/00111		
CERTIFICATE NUMBER	QC240130-06		

### CUSTOMER DETAILS

Name : **Egyptian Maintenance Company(EMC) IRAQ**  
 Address : Iraq, Basra, North Rumaila

### EQUIPMENT IDENTIFICATION AND SPECIFICATIONS

Description : **AC YOKE**  
 Manufacturer : Magnaflux  
 Model : Y-7  
 Serial Number: 1941  
 Part Number : 620741  
 Calibrated By : Asjad Rafiq  
 Calibration Date : January 30, 2024  
 Calibration Due : **Six(6) Months from the date of calibration, (Where Required July 29, 2024)**  
 Calibration Site : QC Labs North Rumaila



### ENVIRONMENTAL CONDITIONS DURING TEST

Ambient Temperature : 22.0 ± 2°C      Humidity : 42.0 ± 5 % RH      Atm. Pressure : 1013.2 ± 10 hPa

### CALIBRATION METHOD

The above equipment has been calibrated in accordance with ASME BPVC-V

### REFERENCE EQUIPMENT USED :

DESCRIPTION	SERIAL NO.	Calibration Date	Due Date
Load Test Plate	APT 1515	20 Nov, 2023	19 Nov, 2024

### CALIBRATION TEST RESULTS

Calibrated Values of Rectangular Plate	PROCEDURE APLLIED	Results
lbs		Pass/Fail
10.00	Yoke Energized, Plate lifted and held firmly.	Pass

**DEVIATION FROM STANDARD METHOD :** None

### REMARK (S) :

- 1 No adjustments were made prior to calibration.
- 2 Overload test was not performed.
- 3 No accessories were fitted.
- 4 Values were rounded in computation.

~ END OF DOCUMENT ~

*This certificate is issued in accordance with the laboratory accreditation requirements as per ISO/IEC17025:2017. This certificate may not be reproduced other than in full, unless permission for the publication of an approved extract has been obtained in writing from the director of QC. It does not of itself impute to the subject of the calibration any attributes beyond those shown by the data contained herein.*