

AI TAKAMUL COMPANY FOR ENGINEERING TESTS  
AND PROFESSIONAL SAFETY LIMITED

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657


Email: [OP@qualitycontrol-iraq.com](mailto:OP@qualitycontrol-iraq.com) / [hany.akafi@qualitycontrol-iraq.com](mailto:hany.akafi@qualitycontrol-iraq.com)



**CERTIFICATE OF THOROUGH EXAMINATION & PROOF LOAD TEST**

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	21/11/2023	Date of Report:	21/11/2023	Certificate No:	QC-23/HALL-2111/18
Client Name:	HALLIBURTON WPS	Location:	TEST AREA	Job Number:	211123

Serial Number:	QTY	Description	SWL	PROOF LOAD TEST	Date of manufacture if known:	Date of last thorough examination
22	1	<p><b>TOP SUB</b></p> 	10,000 LBS	12,000 LBS	N/A	23/08/2023

Reference Standard: HAL DOC: ST-GL-HAL-HSE-0420

Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?	YES	✓	NO	✓
	YES	NO	✓		YES	✓	NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	✓		YES	✓	NO	✓
	YES	NO	✓		YES	✓	NO	✓

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE

Is the above a defect which is of immediate danger to persons: YES  NO



Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: (If none state NONE)

The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory

IS THIS EQUIPMENT SAFE TO OPERATE? YES  NO

Name of Inspector:	Name of person authenticating this report:	Signature & Stamp:	
ASHRAF ELSAID	AIZAZ FARHAT	<p><b>ALI Talib HB48903</b> Date: 22-11-2023 Signature  Haliburton</p>	
Date of Next Through Examination:	20/05/2024		

REV: 00 Dated: 30 May 2021



**THIS IS TO CERTIFY THAT;** a competent person did attend the above mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

