

**AI TAKAMUL COMPANY FOR ENGINEERING TESTS
AND PROFESSIONAL SAFETY LIMITED**

Basra, North Rumaila, Quality Control Yard - Iraq




Tel: +9647834966105 / +9647834964657

Email: ashraf.said@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	29/07/2024	Date of Report:	29/07/2024	Certificate No:	QC-24/HAL.2907.001				
Client Name:	HALLIBURTON	Location:	FMG	Job Number:	290724				
Manufacturer / Date:	CATERPILLAR 2012	Model:	DP70E1	SWL:	7000 KG				
Serial No.:	AT20C70473	Chasses No:	AT20C70473	SAP No:	12259786				
Description of Equipment	<p><u>Diesel Engine Powered Hydraulic System Wheel Loader Forklift Truck.</u></p> <p><i>Max Capacity : 7000 KG</i> <i>Manufacture : CATERPILLAR</i> <i>Max Fork Height : 4560 MM</i> <i>Truck Weight : 10015 KG</i></p> 								
Ref. Standard	BS ISO 2330:2002 / BS ISO 5057:1993								
Date of Last Examination:	27-MAR-2022		Date of Last Proof Load Test:	10-MAY-2017					
TESTING	Pass	Fail	Notes						
Operational (No Load)	✓		Forklift Found Satisfactory For Further Use.						
Performance Test (Rated Capacity)	✓		Forklift found to be acceptable to lift 100 % from SWL .						
Proof Load Test (1.1 x Rated Capacity)	-	-	Proof Load Test Shall Be Done After any Repair/ Modification						
Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓	Was the examination carried out: Within an interval of 6 months?	YES	NO	✓		
				Within an interval of 12 months?	YES	NO	✓		
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO		In accordance with an examination scheme?	YES	NO			
				After the occurrence of exceptional circumstances?	YES	NO	✓		
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE									
Is the above a defect which is of immediate danger to persons:							YES	NO	✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)							N/A		
Particulars of any repair, renewal or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination: (If none state NONE)									
In the light of inspection findings subject Forklift was Inspected visually, operationally and performance test was performed where no defects were observed during testing Hence, it was found satisfactory and fit for intended use.									
IS THIS EQUIPMENT SAFE TO OPERATE?							YES	NO	✓
Name of Inspector:	Name of person authenticating this report:		Signature & Stamp:						
ASHRAF ELSAID	MOHAMED ABDALLAH								
Date of Next Through Examination:	28/07/2025								

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

**AI TAKAMUL COMPANY FOR ENGINEERING TESTS
AND PROFESSIONAL SAFETY LIMITED**

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647834966105 / +9647834964657

Email: ashraf.said@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Halliburton	Location:	FMG	Examination Date:	29/07/2024
Manufacturer / Date:	CATERPILLAR 2012	Model:	DP70E1	SWL:	7000 KG
Serial No.:	AT20C70473	Chasses No:	AT20C70473	SAP No:	12259786

No	COMPONANT CHECKS	RESULT	COMMENTS
DATA PLATE			
1	Manufacturers data plate	√	
MAST/Boom			
1	Operation	√	
2	Structure and welds	√	
3	Rollers & bearings	√	
4	Main hoist cylinder(s)	√	
5	Load chains	√	
6	Anchor pins	√	
7	Tilt cylinders	√	
8	Hydraulic hoses	√	
9	Side shift	√	
FORKS			
1	Condition	√	
2	Heel wear	√	
3	Locking pins	√	
POWER PACK			
1	Operation	√	
2	Engine/motor	√	
3	Mountings	√	
4	Battery	√	
5	Wiring	√	
6	Hydraulic pump	√	
7	Isolation switches	√	

Name of Inspector:	Name of person authenticating this report:	Signature & Stamp:	
ASHRAF ELSAID	MOHAMED ABDALLAH		
Date of Next Through Examination:	28/07/2025		

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

**AI TAKAMUL COMPANY FOR ENGINEERING TESTS
AND PROFESSIONAL SAFETY LIMITED**

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647834966105 / +9647834964657

Email: ashraf.said@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Halliburton	Location:	FMG	Examination Date:	29/07/2024
Manufacturer / Date:	CATERPILLAR 2012	Model:	DP70E1	SWL:	7000 KG
Serial No.:	AT20C70473	Chasses No:	AT20C70473	SAP No:	12259786

No	COMPONANT CHECKS	RESULT	COMMENTS
STEERING AND WHEELS			
1	Operation	√	
2	Steering cylinders	√	
3	Braking system	√	
4	Ball joints	√	
5	Wheel bearings	√	
6	Tire condition	√	
CABIN & CONTROLS			
1	Condition	√	
2	Control levers	√	
3	Control pedals	√	
4	Internal/external lights	√	
5	Gauges	√	
6	Seat and seat belt	√	
7	Horn	√	
8	Windscreen and wipers	N/A	
OTHER			
1	Light Alarm	√	
2	Sound Alarm	√	

Key Category:

1 = Immediate action	2= Action within ...	3= Worn/Serviceable	✓ No Apparent Defects	N/A = Not Applicable
----------------------	----------------------	---------------------	-----------------------	----------------------

Name of Inspector:	Name of person authenticating this report:	Signature & Stamp:	
ASHRAF ELSAID	MOHAMED ABDALLAH		
Date of Next Through Examination:	28/07/2025		

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.