




## Visual & Magnetic Particles Examination Report


<b>Client Name:</b>	Zhongman Petroleum Engineering Technology Service (Hong Kong) Co. Limited Iraq Branch	<b>Location:</b>	ZPEC Rig 20	<b>Job Number:</b>	QC-23-1509
<b>Date of Examination:</b>	01-11-2023	<b>Date of Report:</b>	01-11-2023	<b>Certificate No:</b>	QC-23-1509-01/10
<b>Unit Serial Number</b>	<b>Description of the examined equipment</b>				<b>EACH LUG SWL</b>
EC10050012	70DZ Drilling Rig SCR House Lifting Lugs				15 TON
<b>Lifting Lugs S/N:</b>	D5 , D6 , D7 , D8 , D9 , D10 , D11 , D12				



<b>Unit Dimension:</b>	L: 13 M , W: 2.9 M X H: 3.1 M	<b>Unit Gross Weight:</b>	33 TON
------------------------	-------------------------------	---------------------------	--------

NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	17-02-2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06-2025
Black Ink	7HF	Batch No:	220605	Due Date	7-1-2025

NDT procedure	
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection	
Identification of any part found to have a defect and a description of the defect:	
None	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:	
None	

<b>ASNT Level II Inspector Name:</b>	<b>Name of person authenticating:</b>	<b>Signature &amp; Stamp:</b>	<b>Date of Next Through Examination:</b>
Aizaz Farhat	Mohamed Abdullah		30-04-2024

REV: 01 Dated: 20 June 2022

**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

