



9 5/8" VAM TOP CASING PUP JOINT VISUAL INSPECTION CERTIFICATE

Client Name:		DAQING DRILLING.CO		Date:	19.MAR.2024		
Location/Rig:		DQ-22(RU-604)		Report No.:	QC-24-03-RS-003		
SPECIFICATION:		API Specification 5A5&5ct,10th Edition /VAM SPECIFICATION			Make-up Loss	5.589	
Wall Thickness	0.472	9 5/8"VAM TOP 47.00PPF VAM TOP L-80			ID: 8.681" OD: 9 5/8" Drift: 8.525"		
Joint designation		Total Length	Visual Thread Inspection			END AREAS	
SERIAL:NO	Actual # on JT.	(m)	Thread Profile Gauge	PIN	BOX		
CPJ1	9 5/8' VAM TOP 47.00# PPF VAM TOP CASING JOINT	1m	OK	OK	OK	READY TO USE	
CPJ2	9 5/8' VAM TOP 47.00# PPF VAM TOP CASING JOINT	1m	OK	OK	OK	READY TO USE	
CPJ3	9 5/8' VAM TOP 47.00# PPF VAM TOP CASING JOINT	3m	OK	OK	OK	READY TO USE	
CPJ4	9 5/8' VAM TOP 47.00# PPF VAM TOP CASING JOINT	3m	OK	OK	OK	READY TO USE	
CPJ5	9 5/8' VAM TOP 47.00# PPF VAM TOP CASING JOINT	3m	OK	OK	OK	READY TO USE	
CPJ6	9 5/8' VAM TOP 47.00# PPF VAM TOP CASING JOINT	5m	OK	OK	OK	READY TO USE	
CPJ7	9 5/8' VAM TOP 47.00# PPF VAM TOP CASING JOINT	5m	OK	OK	OK	READY TO USE	
CPJ8	9 5/8' VAM TOP 47.00# PPF VAM TOP CASING JOINT	5m	OK	OK	OK	READY TO USE	
Inspector Name:			Review By				
Qualification:			Senior Inspector:	M.FAHAD	Supervisor:	M.WAQAS	Customer Name:
Signature:							Customer Signature:

Original - Client Files

Copy - Area Office

QC/FN/DJ-PB/029 Rev.00 dated 07.Nov2021

