



Visual & Magnetic Particles Examination Report

| | | | | | |
|---------------------------|--|-----------------------------|------------|------------------------|-------------------------|
| Client Name: | Ecolog International FZE | Date of Examination: | 16-03-2024 | Job Number: | QC-Ecolog-03-24-0087 |
| Location: | Ecolog International FZE Yard Basra Iraq | | | Certificate No: | QC-Ecolog-03-24-0087-01 |
| Unit Serial Number | Description of the examined equipment | | | | Result |
| ECO-1 | Connection Of Jack Truck | | | | Pass |



NDT Equipment Details

| | | | | | |
|----------------|-----------|--------------------|---------------|----------|------------|
| Standard | ASTM E709 | Viewing Condition: | Colored Media | Method | WET |
| Yoke | Permanent | Serial No: | PY-09 | Due Date | 15-08-2024 |
| White Contrast | WCP-2 | Batch No: | 220602 | Due Date | 06-2025 |
| Black Ink | 7HF | Batch No: | 220605 | Due Date | 7-1-2025 |

NDT procedure

Visual and MPI carried out for the above description and found free of surface defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

None

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

None

| | | | |
|--------------------------------------|---------------------------------------|--|--|
| ASNT Level II Inspector Name: | Name of person authenticating: | Signature & Stamp: | Date of Next Through Examination: |
| Abdullah Mofeed | Mohamed Abdullah |  | 15-09-2024 |

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

