

**AI TAKAMUL COMPANY FOR ENGINEERING TESTS
AND PROFESSIONAL SAFETY LIMITED**

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

| | | | | | |
|---|--|---|------------|------------------------|---|
| Date of Examination: | 27/03/2024 | Date of Report: | 27/03/2024 | Certificate No: | QC-24/HALL--2703-02 |
| Client Name: | HALLIBURTON | Location: | HPS | Job Number: | 170324 |
| Serial Number: | QTY | Description | | | Date of last thorough examination |
| 1986195-37 2129088-22 1986195-28 2129088-15 | 04 | <p align="center">ENDLESS POLYSTER ROUND SLING FLOW LINE SAFETY RESTRAINTS</p> <p>MANUFACTURE: WEIR SPM</p> <p>EFFECTIVE LENGTH: 15 FT</p> <p>PN: P23625-D</p> | | | N/A |
| Reference Standard: | PROCEDURE NO 4S24036 REV 1/ HAL DOC: WM-GL-HAL-HSE-0420F & WM-GL-HAL-HSE-0420C REV 1 | | | | |
| Is this the first examination after Installation or assembly at a new site or location? | | YES | NO | ✓ | Was the examination carried out: Within an interval of 6 months? |
| | | | | | YES |
| | | | | | With an interval of 12 months? |
| | | | | | YES |
| If the answer to the above question is YES has the equipment been installed correctly? | | YES | NO | | In accordance with an examination scheme? |
| | | | | | YES |
| | | | | | After the occurrence of exceptional circumstances? |
| | | | | | YES |
| Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE | | | | | |
| Is the above a defect which is of immediate danger to persons: | | | | | YES |
| Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) | | | | | N/A |
| Particulars of any repair, renewal or alteration required to remedy the defect identified above: | | | | | |
| Particulars of any tests carried out as part of the examination: (If none state NONE) | | | | | |
| The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory | | | | | |
| IS THIS EQUIPMENT SAFE TO OPERATE? | | | | | YES |
| | | | | | ✓ |
| | | | | | NO |
| Name of Inspector: | | Name of person authenticating this report: | | | |
| ASHRAF ELSAID | | AIZAZ FARHAT | | | |
| | | Signature & Stamp: | | | |
| Latest date by which next thorough examination must be carried out: 26/09/2024 | | | | | |

REV: 00 Dated: 30 May 2021

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

