



VISUAL & DYE PENETRANT EXAMINATION REPORT

Client Name:	Ecolog International FZE	Date of Examination:	16-03-2024	Job Number:	QC-Ecolog-03-24-0087
Location:	Ecolog International FZE Yard Basra Iraq			Certificate No:	QC-Ecolog-03-24-0087-03

Serial Number	Description of the examined equipment	Result
ECO-3	Connection Of Jack Truck	Pass




NDT Equipment Details

Standard	API STD 53 CAT-IV & ASTM E165	Viewing Condition:		Colored Media		Method	WET
Red Penetrant Manufacture:	Magnaflux	Batch No:	220511	Due Date	05-2025		
Developer Manufacture:	Magnaflux	Batch No:	220302	Due Date	03-2025		

NDT procedure

VISUAL, THOROUGH EXAMINATION	Above Item fully inspected and found freedom from deforms, cracks, corrosion & mechanical damage
DYE PENETRANT INSPECTION (DPI)	forge areas inspected and found freedom from cracks and other defects
None	
All DPI Performed as Per Instructions of OEM:	

ASNT Level II Inspector Name:	Name of person authenticating:	Signature & Stamp:	Date of Next Through Examination:
Abdullah Mofeed	Mohamed Abdullah		15-09-2024

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.